


## 22. 회룡터널 토공노반(G57)

---






|    |                  |            |    |    |     |
|----|------------------|------------|----|----|-----|
| 위치 | STA. 122K160-170 | 선별         | T1 | 위치 | TCL |
| 내용 | 파손               | A= 0.1x0.1 |    |    |     |



|    |                  |             |    |    |    |
|----|------------------|-------------|----|----|----|
| 위치 | STA. 122K380-390 | 선별          | T1 | 위치 | 침목 |
| 내용 | 경계부 균열           | Cw= 0.2/2.2 |    |    |    |




|    |                  |             |    |    |    |
|----|------------------|-------------|----|----|----|
| 위치 | STA. 122K250-260 | 선별          | T2 | 위치 | 침목 |
| 내용 | 경계부 균열           | Cw= 0.2/2.2 |    |    |    |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 122K140-150 | 선별          | T1 | 위치 | TCL |
| 내용 | 균열               | Cw= 0.1/0.4 |    |    |     |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 122K350-360 | 선별          | T2 | 위치 | TCL |
| 내용 | 균열               | Cw= 0.1/0.4 |    |    |     |



|    |                  |             |    |    |     |
|----|------------------|-------------|----|----|-----|
| 위치 | STA. 122K150-160 | 선별          | T2 | 위치 | TCL |
| 내용 | 균열               | Cw= 0.1/0.4 |    |    |     |