

호남고속선 부산고가_91(22.313~22.321km, S17-3)

[illegible]

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	강제부 균열	0.2 mm	0.8 m		56				
2	강제부 균열	0.2 mm	0.5 m		57				
3	강제부 균열	0.2 mm	0.5 m		58				
4	강제부 균열	0.2 mm	0.5 m		59				
5	강제부 균열	0.2 mm	0.8 m		60				
6	강제부 균열	0.2 mm	0.6 m		61				
7	강제부 균열	0.2 mm	0.8 m		62				
8	균열	0.2 mm	0.4 m		63				
9	균열	0.2 mm	0.4 m		64				
10	강제부 균열	0.1 mm	0.7 m		65				
11	균열	0.1 mm	0.7 m		66				
12	균열	0.1 mm	0.7 m		67				
13	균열	0.1 mm	0.4 m		68				
14	균열	0.1 mm	0.4 m		69				
15	균열	0.1 mm	0.4 m		70				
16	균열	0.1 mm	0.4 m		71				
17	균열	0.1 mm	0.4 m		72				
18	균열	0.2 mm	0.5 m		73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	여	용	여	사	간								
								과	인	장	아	지				
KORAIL KOREA RAILROAD	한국철도공사	2017년도	호남고속선	오송-광주승정리	콘크리트케도	점검용역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이복영	김윤강 김경기 문준기	조원	02220 (0.3m이하 : 목책)		천문도상방리		재로방리	
											04220 (0.3m초과 0.5m이하 : 광책)		영상		철근노출	
											06220 (0.5m초과 1.0m미만 : 목책)		박리, 박락, 파손		누수 습윤 부	
											10220 (1.0m이상 : 통책)		변태		시공이음판리, 종판리	