

한남고수선 표본 30 (36.779~36.787, S6-2)

36K779		36K780		36K787	
PCL상면		PCL상면		PCL상면	
TCL측면		TCL측면		TCL측면	
TM.261.3	TM.234.3	TM.245.1	TM.234.1	TM.245.1	TM.234.1
1	1	1	1	1	1
2	2	2	2	2	2
3	3	3	3	3	3
4	4	4	4	4	4
5	5	5	5	5	5
6	6	6	6	6	6
7	7	7	7	7	7
8	8	8	8	8	8
9	9	9	9	9	9
10	10	10	10	10	10
11	11	11	11	11	11
12	12	12	12	12	12
13	13	13	13	13	13

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1	0.7 m		56				
2	균열	0.1	0.7 m		57				
3	균열	0.2	0.4 m		58				
4	균열	0.2	0.3 m		59				
5	균열	0.1	0.7 m		60				
6	균열	0.2	0.3 m		61				
7	균열	0.1	0.4 m		62				
8	균열	0.1	0.4 m		63				
9	균열	0.1	0.4 m		64				
10	균열	0.1	0.7 m		65				
11	균열	0.1	0.4 m		66				
12	균열	0.1	0.4 m		67				
13	균열	0.1	0.4 m		68				
14	균열	0.1	0.4 m		69				
15	균열	0.1	0.4 m		70				
16	균열	0.1	0.4 m		71				
17	균열	0.1	0.4 m		72				
18	균열	0.1	0.4 m		73				
19	균열	0.2	0.4 m		74				
20	균열	0.1	0.7 m		75				
21	균열	0.1	0.7 m		76				
22	균열	0.1	0.7 m		77				
23	균열	0.1	0.7 m		78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	역	영	사	단		
							과업 책임지	장 아 지	
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 복 영	간 윤 강 김 경 기 문 석 기	영원	 02220 (0.3mm이하 : 흑색)	 점도도상판리	 재료판리
							 04220 (0.3mm초과 0.5mm이하 : 황색)	 영상	 철근노출
							 06220 (0.5mm초과 1.0mm미만 : 적색)	 바리,바라,파손	 누수수온부
							 14220 (1.0mm이상 : 홍색)	 변태	 시공이음판리,홍판리
									