

하남고속터미널-토공노반-76(43.060~43.070km, L=10m)

43K060

43K070

[illegible]

하
00

(하)

TCL상면

TM.237.4

채움콘크리트

0.2/1

TCL상업

KR18-025

KR18-04C

12 (40)

(상행)

HSB 3rd Plan	HSB 4th Plan	TCL 3rd Plan	TCL 4th Plan
			1
			2
			3
			4
		② 15.0.1/0.6	5
			6
		② 15.0.1/0.6	7
		② 15.0.1/0.6	8
		② 15.0.1/0.6	9
			10
		② 15.0.2/0.6	11
		② 15.0.1/0.6	12
		② 15.0.1/0.6	13
			14
		② 15.0.1/0.6	15
		② 15.0.1/0.6	16
		② 15.0.1/0.6	

연번	순차	폭	연장	비고	연번	순차	폭	연장	비고
1	균열	0.2 mm	0.4 m		56	균열	0.1 mm	0.6 m	
2	균열	0.2 mm	0.8 m		57	균열	0.1 mm	0.3 m	
3	균열	0.2 mm	0.4 m		58	균열	0.1 mm	0.3 m	
4	균열	0.1 mm	0.8 m		59	균열	0.2 mm	0.6 m	
5	균열	0.2 mm	0.4 m		60	균열	0.1 mm	0.6 m	
6	균열	0.1 mm	0.3 m		61	균열	0.1 mm	0.3 m	
7	균열	0.2 mm	0.4 m		62	균열	0.1 mm	0.6 m	
8	균열	0.1 mm	0.8 m		63	균열	0.1 mm	0.6 m	
9	균열	0.1 mm	0.5 m		64	균열	0.1 mm	0.6 m	
10	균열	0.1 mm	0.4 m		65	균열	0.1 mm	0.6 m	
11	균열	0.1 mm	0.8 m		66	균열	0.4 mm	1.4 m	
12	균열	0.2 mm	0.8 m		67	균열	0.1 mm	0.5 m	
13	균열	0.2 mm	0.4 m		68	균열	0.1 mm	0.5 m	
14	균열	0.1 mm	0.8 m		69	균열	0.2 mm	1.5 m	
15	균열	0.1 mm	0.4 m		70	균열	0.1 mm	0.3 m	
16	균열	0.1 mm	0.8 m		71				
17	균열	0.2 mm	0.4 m		72				
18	균열	0.2 mm	0.8 m		73				
19	균열	0.1 mm	0.4 m		74				
20	균열	0.1 mm	0.8 m		75				
21	균열	0.2 mm	0.4 m		76				
22	균열	0.2 mm	0.5 m		77				
23	균열	0.2 mm	0.8 m		78				
24	균열	0.2 mm	0.8 m		79				
25	균열	0.2 mm	0.4 m		80				
26	균열	0.1 mm	0.5 m		81				
27	균열	0.2 mm	0.4 m		82				
28	균열	0.1 mm	0.8 m		83				
29	균열	0.1 mm	0.4 m		84				
30	균열	0.1 mm	0.5 m		85				
31	균열	0.2 mm	0.8 m		86				
32	균열	0.2 mm	0.4 m		87				
33	균열	0.1 mm	0.8 m		88				
34	균열	0.2 mm	0.8 m		89				
35	균열	0.2 mm	0.4 m		90				
36	균열	0.2 mm	0.5 m		91				
37	균열	0.1 mm	0.8 m		92				
38	균열	0.2 mm	0.8 m		93				
39	균열	0.1 mm	0.8 m		94				
40	균열	0.1 mm	0.5 m		95				
41	균열	0.2 mm	0.4 m		96				
42	균열	0.1 mm	0.8 m		97				
43	균열	0.2 mm	0.4 m		98				
44	균열	0.1 mm	0.5 m		99				
45	균열	0.2 mm	0.4 m		100				
46	균열	0.2 mm	0.5 m		101				
47	균열	0.2 mm	0.8 m		102				
48	균열	0.2 mm	0.4 m		103				
49	균열	0.1 mm	0.5 m		104				
50	균열	0.2 mm	0.8 m		105				
51	균열	0.1 mm	0.8 m		106				
52	균열	0.1 mm	0.4 m		107				
53	균열	0.1 mm	0.6 m		108				
54	균열	0.1 mm	0.6 m		109				
55	균열	0.1 mm	0.6 m		110				

시	행 사	영 역	영 역	영 역	사	인 지		단	
						과 업	아 지		
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검공역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 박 영	강 완 강 김 경 기 윤 석 기	영역	 0220 (0.3m이하 : 흑색)	 참목도상본리	
							 0420 (0.3m초과 0.5m이하 : 황색)		 양상
							 0620 (0.5m초과 1.0m이하 : 적색)		 바닥,벽면,파손
							 1020 (1.0m이상 : 분홍색)		 백태
							 0220	 시공이음본리,종본리	