

호남고속선 장구교_111(49.265~49.272km, S22-5)

49K265

P22
49K272

22 SPAN-5

22 SPAN-5

[illegible]

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	강제부 균열	0.3	0.3	m	55				
2	균열	0.1	mm	0.4	m	56			
3	균열	0.1	mm	0.4	m	57			
4	강제부 균열	0.3	mm	0.3	m	58			
5	강제부 균열	0.3	mm	0.3	m	59			
6	균열	0.1	mm	0.5	m	60			
7	균열	0.1	mm	0.3	m	61			
8	균열	0.1	mm	0.4	m	62			
9	균열	0.2	mm	0.4	m	63			
10	균열	0.1	mm	0.3	m	64			
11	균열	0.1	mm	0.4	m	65			
12	균열	0.1	mm	0.4	m	66			
13	균열	0.1	mm	0.4	m	67			
14	균열	0.2	mm	0.4	m	68			
15					69				
16					70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시	행 사	명	여 명	영 사	영 여 사	구 간							
						관 령 인 자	장 의 장 인 자						
 한국철도공사 KOREA RAILROAD	한국의 고속선 오승광주송정간 특급리테이크도 정검을여	2017년도	호남고속선	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 박 영 김 경 기 윤 작 기	강 원 강 김 경 기 윤 작 기	영 권		0220 (0.3mm이하 : 황색)		천문도상본리		재료본리
									0420 (0.3mm초과 0.5mm이하 : 청색)		망상		철근노출
									0820 (0.5mm초과 1.0mm미만 : 적색)		바닥,벽면,파손		누수,슬래브
									1020 (1.0mm이상 : 분홍색)		백태		시공이음본리,종본리
									1220 (분홍색)		백태		시공이음본리,종본리
									1420 (분홍색)		백태		시공이음본리,종본리