


한남고속선 장구교-137(49.447~49.454km, S28-1)

P27

49K447

49K454

28 SPAN -1



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.3 m		55				
2	강재부 균열	0.3 mm	0.3 m		56				
3	강재부 균열	0.3 mm	0.3 m		57				
4	강재부 균열	0.3 mm	0.3 m		58				
5	균열	0.1 mm	0.3 m		59				
6	균열	0.1 mm	0.3 m		60				
7	균열	0.1 mm	0.3 m		61				
8	강재부 균열	0.3 mm	0.3 m		62				
9	균열	0.1 mm	0.4 m		63				
10	균열	0.1 mm	0.4 m		64				
11	강재부 균열	0.3 mm	1.0 m	같이줄기	65				
12	균열	0.2 mm	0.5 m		66				
13	균열	0.1 mm	0.3 m		67				
14					68				
15					69				
16					70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역	영역	영역	사	이부영		구분			
					과일전입지	정보이별책일지				
KORAIL KOREA RAILROAD 한국철도공사	2017년도 호남고속선 오송-광주승점간 콘크리트캐드 점검공역	(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원	이부영	김윤강 김경기 문적기	영원		0220 (0.3m이하 : 흑석)		재료분리	
							0420 (0.3m초과 0.5m이하 : 형석)		망상	
							0620 (0.5m초과 1.0m미만 : 직석)		박리, 박락, 파손	
							1020 (1.0m이상 : 불용석)		번데	
									누수, 침윤부	
									사이클음 분리, 총분리	