


호남고속선 장구교_177(49.727~49.734km, S36-1)

P35
49K727

49K734

36 SPAN - 1



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		55				
2	균열	0.1 mm	0.75 m		56				
3	균열	0.1 mm	0.3 m		57				
4	균열	0.1 mm	0.75 m		58				
5	균열	0.1 mm	0.75 m		59				
6	균열	0.1 mm	0.7 m		60				
7	균열	0.1 mm	0.3 m		61				
8	균열	0.1 mm	0.3 m		62				
9	경계부 균열	0.1 mm	0.6 m		63				
10	균열	0.1 mm	0.4 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.3 m		67				
14	균열	0.1 mm	0.7 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.5 m		70				
17	균열	0.1 mm	0.6 m		71				
18	균열	0.1 mm	0.7 m		72				
19	균열	0.1 mm	0.6 m		73				
20	균열	0.1 mm	0.3 m		74				
21	균열	0.1 mm	0.3 m		75				
22	균열	0.1 mm	0.3 m		76				
23	균열	0.1 mm	0.3 m		77				
24	균열	0.1 mm	0.3 m		78				
25	경계부 균열	0.3 mm	0.4 m		79				
26	균열	0.1 mm	0.6 m		80				
27	균열	0.1 mm	0.7 m		81				
28	균열	0.1 mm	0.3 m		82				
29	균열	0.1 mm	0.6 m		83				
30	균열	0.1 mm	0.7 m		84				
31	경계부 균열	0.3 mm	1.0 m	신구	85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행	사	영역	영역	영역	사	과업책임자		장비책임자	근거	참목도상분리	재료분리	
						과업책임자	장비책임자					
한국철도공사 KORAIL Korea Railroad						(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설기술연구원		이복영	리영강 김경기 윤석기	 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.220 (0.3mm이하 : 흑색)  0.420 (0.5mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm미만 : 적색)  1.020 (1.0mm이상 : 분홍색)	 참목도상분리  양상  배리, 배리, 파손  배리	 배리  배리  배리  배리
										 0.2		