

호남고속선 정지코가_1217(65.361~65.368km, S233-2)

PCL상면		TCL측면		TCL상면		PCL상면		TCL측면		TCL상면		PCL상면		TCL측면		TCL상면		PCL상면	
65K361																			
TM.259.3																			
TM.086.4																			
TM.047.3																			
TM.100.1																			

연번	순번	종	연장	비고	연번	순번	종	연장	비고
1	균열	0.1 mm	0.4 m		56				
2	균열	0.2 mm	0.7 m		57				
3	균열	0.1 mm	0.4 m		58				
4	균열	0.1 mm	0.4 m		59				
5	균열	0.1 mm	0.4 m		60				
6	균열	0.1 mm	0.4 m		61				
7	균열	0.1 mm	0.4 m		62				
8	균열	0.1 mm	0.5 m		63				
9	균열	0.1 mm	0.6 m		64				
10	균열	0.1 mm	0.4 m		65				
11	균열	0.1 mm	0.5 m		66				
12	균열	0.1 mm	0.4 m		67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54									

시 행 사	공 영 명	공 역 사	구 단		구 단 명	구 단 상 징
			과 업 배 임 지	장 아 지		
KORAIL 한국철도공사 KOREA RAILROAD	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검영역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설철물연구원	이 복 영		간 음 경 김 경 기 문 은 석 기	 0222 (0.3mm이하 : 불식)  0420 (0.3mm초과 0.5mm이하 : 평식)  0620 (0.5mm초과 1.0mm이하 : 적식)  1020 (1.0mm이상 : 분출식)  1020 (1.0mm이상 : 분출식)
			철도도상본리			
			철근노출			
			누수, 슬관부			
			시공이음본리, 종본리			