

호남고속선 정지 고가_416(59.796~59.803km, S79-4)

59K796

59K803
79 SPAN - 4

79 SPAN - 4

PCL상표

TCL 集团	TCL 产业
--------	--------

TM.248.2	16.0	0.1/0.5	16.0	15.0	TM.091.1
----------	------	---------	------	------	----------

TM.091.1

TCL 405	TCL 405
TCL 405	TCL 405

PCL 시험

15

TCL 추면	TCL 상면
--------	--------

TM.280.4	0.1/0.7	0.1/0.7	0.1/0.7	0.1/0	TM.2202

TM.220.2

TCL 4000	TCL 4000
----------	----------

PCL상표

연번	순차	목	연장	비고	연번	순차	목	연장	비고
1	균열	0.1 mm	0.4 m		56				
2	균열	0.1 mm	0.6 m		57				
3	균열	0.1 mm	0.3 m		57				
4	균열	0.1 mm	0.3 m		58				
5	균열	0.1 mm	0.4 m		59				
6	균열	0.1 mm	0.7 m		60				
7	균열	0.1 mm	0.7 m		61				
8	균열	0.1 mm	0.7 m		62				
9	균열	0.1 mm	0.3 m		63				
10	균열	0.1 mm	0.3 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.2 mm	1.0 m		69				
16	균열	0.1 mm	0.5 m		70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

 한국철도공사 KOREA RAILROAD	시행사	공역명	용역사항	이력영		구분			
			(주) 한국구조물안전연구원 (주) 한국토목안전연구원 (재) 한국건설품질연구원	과업책임자	장비관리자	감문강 김경기 윤석기			
						천문도시상본리		재료본리	
						양산		철근노출	
						바다, 파라, 파손		누수, 슬림부	
						백태		서귀읍본리(충본리)	
						2.020			