

호남고속선 신작교_91(67.108~67.115km, S18-5)

67K108

67K115

18 SPAN - 5

PCL상

14	16-0.1/0.4
----	------------

TCL	TCL
상	상
면	면

TM.053.4

TM.161.3

아
아

(아
아)

TCL 상면	TCL 측면
--------	--------

PCL 508

TCL	TCL
상	상
면	면

TM.131.2

T2
(0주
0앞)

(유한)

TCL 상	TCL
TCL	TCL

PCL상표

[

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	경계부 균열	0.2 mm	0.6 m		55				
2	경계부 균열	0.2 mm	0.6 m		56				
3	경계부 균열	0.2 mm	0.6 m		57				
4	경계부 균열	0.2 mm	0.6 m		58				
5	균열	0.2 mm	0.4 m		59				
6	균열	0.2 mm	0.4 m		60				
7	균열	0.2 mm	0.3 m		61				
8	균열	0.2 mm	0.4 m		62				
9	균열	0.2 mm	0.3 m		63				
10	균열	0.2 mm	0.3 m		64				
11	균열	0.2 mm	0.4 m		65				
12	균열	0.2 mm	0.4 m		66				
13	양상 균열	0.6 m	6.5 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.4 m		72				
19	균열	0.1 mm	0.2 m		73				
20	균열	0.1 mm	0.4 m		74				
21	균열	0.1 mm	0.4 m		75				
22	균열	0.1 mm	0.3 m		76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역명	공여회사	이 박 영				연간	노선도상분리	차량운출				
			과업책임자	장의책임자	분야별책임자								
KORAIL 한국철도공사 KOREA RAILROAD	2017년도 호남고속선 오송-광주승정간 콘크리트케드 점검용역	(주) 한국구조물안전연구원 (주) 한국도로교통안전연구원 (재) 한국건설품질연구원	김민경 안석기	02220 (0.3mm이하 : 흑색)	한목도상분기								
									04420 (0.3mm초과 0.5mm이하 : 청색)	망상			
08620 (0.5mm초과 1.0mm이하 : 적색)	바닥, 벽락, 파손												
11020 (1.0mm이상 : 분홍색)	변태												