


호남고속선 죽산교_323(75.297~75.304km, S65-2)


75K304

75K297


$$\left(\begin{array}{c} \text{아} \\ \text{0} \end{array} \right)$$

(아
아)

PCL상면



T2
(0_T 0_H)

(악향)

연번	순차	폭	연장	비고	연번	순차	폭	연장	비고
1	군열	0.2 mm	0.65 m		55				
2	군열	0.1 mm	0.3 m		56				
3	군열	0.1 mm	0.7 m		57				
4	군열	0.1 mm	0.7 m		58				
5	군열	0.2 mm	0.3 m		59				
6	군열	0.2 mm	0.65 m		60				
7	군열	0.1 mm	0.7 m		61				
8	군열	0.2 mm	0.65 m		62				
9	군열	0.2 mm	0.65 m		63				
10	군열	0.2 mm	0.65 m		64				
11	군열	0.2 mm	1.2 m		65				
12	군열	0.2 mm	1.2 m		66				
13	군열	0.2 mm	0.4 m		67				
14					68				
15					69				
16					70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시	행	사	영	역	영	영	역	사	이		영			
									관	인		장	아	
									관	인	장	아		
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역						(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 부영	간원강 김경기 문은석	영	 0220 (0.3mm이하 : 흑색)	 점목도상판리	 재료판리
												 0420 (0.3mm초과 0.5mm이하 : 황색)	 망상	 철판노출
												 0620 (0.5mm초과 1.0mm이하 : 적색)	 박리, 박락, 표손	 누수, 습윤부
												 1020 (1.0mm이상 : 분홍색)	 백태	 시공이음판리, 종판리
												 1220	 노상	 노상