


호남고속선 죽산교_325(75.311~75.318km, S65-4)

75K311


75K318



아
0

(아
아)

PCL상면



12월 09일

(유형)

연번	산선	폭	연장	비고	연번	산선	폭	연장	비고
1	균열	0.1 mm	0.7 m		55				
2	균열	0.1 mm	0.7 m		56				
3	균열	0.2 mm	0.65 m		57				
4	강계부 균열	0.3 mm	0.3 m		58				
5	균열	0.1 mm	0.7 m		59				
6	강계부 균열	0.3 mm	0.3 m		60				
7	균열	0.1 mm	0.7 m		61				
8	균열	0.2 mm	0.7 m		62				
9	균열	0.2 mm	0.65 m		63				
10	균열	0.1 mm	0.7 m		64				
11	균열	0.1 mm	0.3 m		65				
12	균열	0.1 mm	0.7 m		66				
13	균열	0.2 mm	0.65 m		67				
14	균열	0.2 mm	0.65 m		68				
15	균열	0.1 mm	0.7 m		69				
16	균열	0.2 mm	0.65 m		70				
17	균열	0.1 mm	0.7 m		71				
18	균열	0.2 mm	0.65 m		72				
19	균열	0.2 mm	0.65 m		73				
20	균열	0.1 mm	0.7 m		74				
21	균열	0.1 mm	0.4 m		75				
22	균열	0.1 mm	0.4 m		76				
23	균열	0.1 mm	0.5 m		77				
24	균열	0.1 mm	0.4 m		78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시	행	사	영	역	영	영	역	사	이		영			
									관	인		장	아	
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역					(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 복영	간 윤강 김 경 기 문 은 석 기	영				
											관	인	장	아
											관	인	장	아
											관	인	장	아
											관	인	장	아
		0220	(0.3mm이하 : 흑색)		점목도상판리		재료판리							
		0420	(0.3mm초과 0.5mm이하 : 황색)		망상		철근노출							
		0620	(0.5mm초과 1.0mm이하 : 적색)		박리, 박락, 파손		누수, 슬럼프							
		1020	(1.0mm이상 : 분홍색)		백태		시공이음판리, 종판리							