

호남고속선 원형제1코_5(77.081~77.088km, S1-5)

77K088
1 SPAN - 5

77K081

TCL측면
TCL상면

TM.126.4

TM.066.3

TCL측면
TCL상면

TCL측면
TCL상면

TM.177k1

TM.006.2

Technical drawing of a roof structure for 77K081, showing two spans (TM.126.4 and TM.066.3) and a section (TM.177k1). The drawing includes dimensions for height and slope, and labels for the roof and floor levels.

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.7 m						
2	균열	0.5 mm	0.8 m						
3	균열	0.5 mm	0.8 m						
4	균열	0.5 mm	0.8 m						
5	균열	0.2 mm	1.1 m						
6	균열	0.2 mm	1.1 m						
7	균열	0.1 mm	0.7 m						
8	균열	0.1 mm	0.7 m						
9	균열	0.1 mm	0.3 m						
10	균열	0.1 mm	0.4 m						
11	균열	0.1 mm	0.7 m						
12	균열	0.1 mm	0.4 m						
13	균열	0.1 mm	0.5 m						

시	행	사	용	여	명	사	이		구간	표												
							점	입														
KORAIL	한국철도공사	KOREA RAILROAD	2017년도 화남고속선 오송-광주승정간 콘크리트케도 점검용역	(주) 한국구조물안전연구원 (주) 한국도로교통연구원 (재) 한국건설품질연구원	이	복	영	리온강 김경기 윤석기	연월	표												
											0.2220 (0.3mm이하 : 흑색)	천등도상판리		재료보관리								
															0.6820 (0.3mm초과 0.5mm이하 : 황색)	임상		철판노출				
																			0.6820 (0.5mm초과 1.0mm이하 : 적색)	바닥 박막, 파손		누수, 슬림부