


87. B29_황등제2교

점검 일자	2017. 07.12~2017. 10.25
평균 기온	25.2 ~ 29.8℃

시 행 사	용 역 명	용 역 사	과 업 담 당 자		구 분	표 시	구 분	표 시	
			과 업 책 임 자	평 가 책 임 자					
 한국철도공사 KOREA RAILROAD	2017년도 호남고속선 오송-광주승정간 콘크리트크레도 점검용역	(주)한국구조물안전연구원 (주)한국국토안전연구원 (재)한국건설품질연구원	이봉영	라영강 김경기 김민석	 0.2/2.0 (0.3mm이하 : 흑색)	침목도상부리		재료부리	
					 0.4/2.0 (0.3mm초과 0.5mm이하 : 청색)	망상		철근노출	
					 0.6/2.0 (0.5mm초과 1.0mm미만 : 적색)	박리, 박락, 파손		누수, 슬럼프	
					 1.0/2.0 (1.0mm이상 : 분홍색)	백태		시공이용불리, 총부리	

외관조사망도 번호
B29_황등제2교_6(82K461~82K468)

82K461



82K59

TM.028.4

TM.030.4

[illegible]

TM.205.1

TM.154.1

11	
10	
9	
8	
7	
6	
5	
4	
3	
2	
1	

[illegible]

외관조사망도 번호
B29_황등제2교_91(83K04~83K047)

83K04

TCL측면
TCL상면

TM.208.1

TCL상면
TCL측면

TCL측면
TCL상면

TM.009.3

TCL상면
TCL측면

[illegible]

