


**2018년 하반기 시설물 정기점검 용역
정 기 점 검 사 진 첩
[4공구 손상현황 사진첩]**


2018. 12.




新 대구부산고속도로주식회사
New DAEGU BUSAN Expressway Co., Ltd.

1.1 삼성1교











	
	
	















1.2 흥산3교









	


	





1.3 흥산2교













	
	
	






1.4 흥산1교


















1.5 원리교




















1.6 남천교























1.7 하도교











1.8 청도2교






















1.9 송읍교

















1.10 하도육교







--


	
	


2.1 청도2터널

















3.1 보강토옹벽



