

**2018년 하반기 시설물 정기점검 용역
정 기 점 검 사 진 첩
[7공구 손상현황 사진첩]**

2018. 12.




新 대구부산고속도로주식회사
New DAEGU BUSAN Expressway Co., Ltd.

1.1 엄남천교























1.2 남기2교







--



1.3 남기1교










1.4 금천교


















1.5 밀양IC교









1.6 밀양IC1교





















1.7 월연교


























1.8 금시교




















1.9 용평2교





--










1.10 용평1교































2.1 고정3터널

















2.2 고정2터널
























	
	
	


2.3 고정1터널



















2.4 가곡터널

