



**2018년 하반기 시설물 정기점검 용역
정 기 점 검 사 진 첵
[10공구 손상현황 사진첩]**


2018. 12.




新 대구부산고속도로주식회사
New DAEGU BUSAN Expressway Co., Ltd.

1.1 감로3교



















1.2 감로2교















	
	
	








1.3 감로1교












	
	








	
	
	







	
	
	





1.4 화현교



--





1.5 상동IC1교






	


	
	
	



1.6 상동IC교






	
	







1.7 상동IC3교

















1.8 상동IC2교











	
	



1.9 대포천교





























1.10 매리교








	








1.11 소감천교


















1.12 덕산교









1.13 덕산육교








--


	
	

1.14 대동JCT5교
















1.15 대동JCT4교











1.16 대동JCT7교











	
	
	



1.17 대동JCT6교










--


2.1 상동2터널


















2.2 상동1터널














3.1 대동판넬진입로 옹벽



