

**2018년 하반기 시설물 정기점검 용역
정 기 점 검 사 진 첵
[2종 절토사면 손상현황 사진첩]**

2018. 12.





新 대구부산고속도로주식회사
New DAEGU BUSAN Expressway Co., Ltd.



1. 부산절토 1 (부산기점 10.86~11.23Km)

















2. 대구절토 2 (부산기점 10.73~11.21Km)







	
	
	
1소단배수로 균열	





3. 부산절토 3 (부산기점 12.45~12.75Km)















4. 부산절토 4 (부산기점 12.97~13.23Km)













5. 부산절토 5 (부산기점 21.92~22.28Km)












6. 대구절토 6 (부산기점 27.73~28.09Km)















7. 부산절토 7 (부산기점 30.75~31.16Km)











8. 부산절토 8 (부산기점 31.16~31.36Km)

















9. 대구절토 9 (부산기점 46.17~46.87Km)











10. 대구절토 10 (부산기점 54.01~54.53Km)











11. 대구절토 11 (부산기점 56.56~56.91Km)











12. 대구절토 12 (부산기점 56.99~57.22Km)











13. 대구절토 13 (부산기점 59.27~59.65Km









14. 부산절토 14 (부산기점 65.94~66.24Km)











15. 부산절토 15 (부산기점 70.77~71.01Km)















16. 부산절토 16 (부산기점 71.58~71.86Km)















17. 대구절토 17 (부산기점 72.74~73.12Km)












18. 대구절토 18 (부산기점 73.38~73.78Km)













19. 대구절토 19 (부산기점 73.80~74.26Km















20. 대구절토 20 (부산기점 76.34~76.65Km)














21. 대구절토 21 (부산기점 77.99~78.37Km














22. 부산절토 22 (부산기점 81.14~81.35Km)












23. 대구절토 23 (부산기점 26.94~27.26Km)
















24. 대구절토 24 (부산기점 49.82~50.0Km)













25. 대구절토 25 (부산기점 50.35~50.55Km)









26. 대구절토 26 (부산기점 51.45~51.65Km)





