

옹벽 상태 진단 결과표

1. 시설물명 : 패널식 옹벽 12

2. 위 치 : 경상북도 영천시 신녕면 화남리(상주영천고속도로 63.430~63.788km)

3. 옹 벽 종 류 : 보강토옹벽 ▼

4. 스펀의 갯수 : 41 ▼

No.	침 하	계획선 형오차	활동	세굴	파손 및 손상	균열	마모 /침식	박리	박락 및 충분리	백태	철근 노출	중성화	영화물	배수공	주변영향인자				결함 점수 합계	평가단위 결함지수	평가단위 평가등급
						이격	유실	침양 상태	진행성 변형	채움면 크기등		암석 분포등	배수 시설		사면조사						
															사면 구배	낙석 흔적	침출수				
1	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
3	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
4	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
5	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
6	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
7	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
8	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
9	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
10	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
11	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
12	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.05	A
13	0	0	0	0	1	0	0	0	0	2	0	0	0	0	0	0	0	0	3	0.02	A
14	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	2	0.05	A
15	0	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	2	0.05	A
16	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
17	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
18	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
19	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0.02	A
21	0	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0	0	0	1	0.02	A
22	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
23	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
24	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
25	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
26	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
27	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
28	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
29	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
30	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
31	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
32	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
33	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
34	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
35	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
36	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
37	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
38	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
39	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
40	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
41	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
평균	0.00	0.00	0.00	0.00	0.22	0.00	0.00	0.00	0.00	0.15	0.00	0.00	0.00	0.00	0.05	0.00	0.00	0.00	0.41	0.01	

상태평가등급

A