

옹벽 상태 진단 결과표

1. 시설물명 : 패널식 옹벽 02

2. 위 치 : 대구광역시 군위군 소보면 달산리(상주영천고속도로 25.414~25.852km)

3. 옹 벽 종 류 : 보강토옹벽 ▼

4. 스펀의 갯수 : 22 ▼

No.	침 하	계획선 형오차	활동	세굴	파손 및 손상	균열	마모 /침식	박리	박락 및 충분리	백대 진행성 변형	IF 철근 노출	증성화 재중권 크리트	영화물 양화토	배수공	주변영향인자				결함 점수 합계	평가단 위 결함지 수	평가단 위 평가등 급
						이격	유실	철망 상태	충분리	진행성 변형		배수 시설	사면조사								
													사면 구배		낙석 흔적	침출수					
1	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
2	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
3	0	0	0	2	2	0	0	0	0	2	0	0	0	0	0	0	0	0	6	0.12	A
4	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2	0.04	A
5	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
6	0	0	0	0	2	0	0	0	0	0	0	0	0	0	0	0	0	0	2	0.04	A
7	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
8	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
9	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
10	0	0	0	0	1	1	0	0	0	0	0	0	0	0	0	0	0	0	2	0.04	A
11	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	0	0	0	1	0.02	A
12	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
13	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
14	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
16	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
17	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
18	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
19	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
20	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
21	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
22	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0.00	A
평균	0.00	0.00	0.00	0.09	0.64	0.05	0.00	0.00	0.00	0.09	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.86	0.02	

상태평가등급

A