

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 수량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존손상	S1	난간,연석	파손	0.70	2.00	30.00	1.40	m²	1	1.68											
2	2020	기존보수	A1	신축이음	후타재 균열(0.3mm미만)	0.20	0.40		4.40	m	11	5.28											
3	2020	기존보수	A1	신축이음	후타재 균열(0.3mm미만)	0.20	0.30		3.30	m	11	3.96											
4	2020	기존보수	A1	신축이음	후타재 균열(0.3mm미만)	0.20	0.40		3.20	m	8	3.84											
5	2020	기존보수	A1	신축이음	후타재 균열(0.3mm미만)	0.20	0.30		3.00	m	10	3.60											
6	2020	기존보수	A1	신축이음	후타재 파손	0.40	0.80		0.32	m²	1	0.38											
7	2020	기존보수	A1	신축이음	신축이음 단차		0.01		0.01	m	1	0.01											
8	2020	기존보수	A1	신축이음	누수(신축이음부)		1.00		1.00	m	1	1.20											
9	2020	기존손상	S1	교면포장	포장망상균열	3.00	1.50		4.50	m²	1	5.40											
10	2020	기존손상	S1	배수시설	배수구 막힘				1.00	ea	1	1.00											
11	2020	기존손상	S1	교면포장	포장균열		6.00		66.00	m	11	79.20											
12	2020	기존손상	S1	교면포장	포장망상균열	3.00	3.00		9.00	m²	1	10.80											
13	2020	기존손상	S1	배수시설	배수구 막힘				1.00	ea	1	1.00											
14	2020	기존보수	S1	난간,연석	파손	0.40	3.00		1.20	m²	1	1.44											
15	2020	기존보수	S1	교면포장	포트홀	0.10	0.10		0.01	m²	1	0.01											
16	2020	기존손상	S1	배수시설	배수구 막힘				1.00	ea	1	1.00											
17	2018	기존손상	S1	교면포장	포장열화	45.00	3.00		135.00	m²	1	162.00											
18	2020	기존손상	S1	배수시설	배수구 막힘				1.00	ea	1	1.00											
19	2020	기존손상	S1	교면포장	포장열화	45.00	0.70		31.50	m²	1	37.80											
20	2021	신규손상	A1	신축이음	후타재 마모	0.40	7.50		3.00	m²	1	3.60											
21	2021	신규손상	S1	난간,연석	균열(0.3mm미만)	0.20	1.00		1.00	m	1	1.20											
22	2021	신규손상	S1	교면포장	포장망상균열	0.60	5.00		3.00	m²	1	3.60											
23	2021	신규손상	S1	교면포장	포장망상균열	2.50	6.00		15.00	m²	1	18.00											
24	2021	신규손상	S1	교면포장	포장균열		2.00		2.00	m	1	2.40											
25	2021	신규손상	S1	난간,연석	균열(0.3mm미만)	0.20	1.00		1.00	m	1	1.20	</										

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 수량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	수량					
1	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
2	2020	기존손상	S3	교면포장	포장상상균열	2.50	2.50		6.25	m²	1	7.50											
3	2020	기존손상	S3	교면포장	포장균열		2.50		5.00	m	2	6.00											
4	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
5	2020	기존손상	S3	교면포장	포장균열		3.00		3.00	m	1	3.60											
6	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
7	2020	기존보수	S3	난간,연석	재료분리	0.20	1.00		0.20	m²	1	0.24											
8	2020	기존손상	S3	교면포장	포장상상균열	5.50	10.00		55.00	m²	1	66.00											
9	2020	기존손상	S3	교면포장	포장균열		2.50		2.50	m	1	3.00											
10	2020	기존손상	S3	교면포장	포장균열		0.50		0.50	m	1	0.60											
11	2020	기존손상	S3	교면포장	포장균열		60.00		60.00	m	1	72.00											
12	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
13	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
14	2020	기존보수	S3	교면포장	포트홀	0.10	0.10		0.01	m²	1	0.01											
15	2020	기존손상	S3	교면포장	포장균열		0.70		0.70	m	1	0.84											
16	2020	기존손상	S3	배수시설	배수구 막힘				1.00	ea	1	1.00											
17	2020	기존손상	S3	난간,연석	균열(0.3mm미만)	0.20	4.80		4.80	m	1	5.76											
18	2021	신규손상	S3	교면포장	포장균열		7.00		7.00	m	1	8.40											
19	2021	신규손상	S3	교면포장	포장패임	0.30	8.00		2.40	m²	1	2.88											
20	2021	신규손상	S3	교면포장	포장상상균열	0.80	10.00		8.00	m²	1	9.60											
21	2021	신규손상	S3	난간,연석	균열(0.3mm미만)	0.20	7.00		7.00	m	1	8.40											
22	2021	신규손상	S3	교면포장	포장패임	0.20	0.60		0.12	m²	1	0.14											
23	2021	신규손상	S3	난간,연석	균열(0.3mm미만)	0.20	4.80		4.80	m	1	5.76											
24	2021	신규손상	S3	난간,연석	균열(0.3mm미만)	0.20	3.00		3.00	m	1	3.60											
25	2021	신규손상	S3	난간,연석	균열(0.3mm미만)	0.20	3.00		3.00	m	1	3.60											
26	2021	신규손상	S3																				

[illegible]

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결합종류	결함규모						보수 물량	보수내역						결함부 사진			외관조사 망도	비 고	
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수				점검
													년월	보수공법	물량	년월	보수공법	물량		2014	2014			
1	2020	기존보수	S1	바닥판	보수부 박락	0.80	0.60		0.48	m²	1	0.576												
2	2020	기존보수	S1	바닥판	백태	1.00	0.20		0.20	m²	1	0.24												
3	2020	기존손상	S1	바닥판	누수흔적	0.50	0.50		0.25	m²	1	0.3												
4	2020	기존보수	S1	바닥판	백태	0.40	1.30		0.52	m²	1	0.624												
5	2020	기존보수	S1	바닥판	백태	1.20	1.00		1.20	m²	1	1.44												
6	2020	기존손상	S1	바닥판	누수흔적	0.50	0.50		0.25	m²	1	0.3												
7	2020	기존보수	S1	PSC BOX 외부	파손	0.50	1.20		0.60	m²	1	0.72												
8	2020	기존보수	S1	PSC BOX 외부	표면보호재 박리	0.70	1.00		0.70	m²	1	0.84												
9	2020	기존보수	S1	바닥판	표면보호재 박리	0.20	0.20		0.04	m²	1	0.048												
10	2020	기존보수	S1	바닥판	표면보호재 박리	0.10	0.10		0.01	m²	1	0.012												
11	2020	기존보수	S1	PSC BOX 외부	백태	2.00	2.00		8.00	m²	2	9.6												
12	2020	기존보수	S1	바닥판	표면보호재 박리	0.30	0.60		0.18	m²	1	0.216												
13	2020	기존보수	S1	바닥판	균열(0.3mm미만)	0.20	1.20		1.20	m	1	1.44												
14	2020	기존보수	S1	바닥판	균열,백태(0.3mm이상)	0.30	0.10		0.10	m	1	0.12												
15	2020	기존손상	S1	바닥판	균열(0.3mm미만)	0.20	1.20		1.20	m	1	1.44												
16	2020	기존손상	S1	바닥판	누수흔적	0.50	0.50		0.25	m²	1	0.3												
17	2020	기존손상	S1	바닥판	누수흔적	0.50	0.50		0.25	m²	1	0.3												
18	2020	기존보수	S1	바닥판	안내표지판 고정불량				1.00	ea	1	1												
19	2021	신규손상	S1	바닥판	백태	0.20	0.60		0.12	m²	1	0.144												
20	2021	신규손상	S1	바닥판	백태	0.30	1.00		0.30	m²	1	0.36												
21	2021	신규손상	S1	PSC BOX 외부	균형	0.10	0.60		0.06	m²	1	0.072												
22	2021	신규손상	S1	PSC BOX 외부	박락	0.30	0.30	50.00	0.09	m²	1	0.108												
23	2021	신규손상	S1	PSC BOX 외부	균형	1.50	1.50		4.50	m²	2	5.4												
24	2021	신규손상	S1	PSC BOX 외부	백태	0.20	0.20		0.04	m²	1	0.048												
25	2021	신규손상	S1	PSC BOX 외부	균형	0.30	3.00		0.90	m²	1	1.08												

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
2	2020	기존손상	S3-G1	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
3	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
4	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.40		1.60	m	4	1.92											
5	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
6	2020	기존보수	S3-G1	PSC BOX 내부	재료분리	0.70	0.30		0.21	m³	1	0.25											
7	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
8	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
9	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	7.80		7.80	m	1	9.36											
10	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
11	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
12	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
13	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
14	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	4.70		4.70	m	1	5.64											
15	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.20	1.50		3.00	m	2	3.60											
16	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.20	1.50		1.50	m	1	1.80											
17	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.50		1.00	m	2	1.20											
18	2020	기존손상	S3-G1	바닥판	균열(0.3mm미만)	0.10	0.40		5.20	m	13	6.24											
19	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
20	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
21	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.80	m	2	0.96											
22	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
23	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.50		1.50	m	1	1.80											
24	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
25	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
26	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		2.00	m	5	2.40											
27	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
28	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.15		0.15	m	1	0.18											
29	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
30	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
31	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
32	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
33	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
34	2020	기존손상	S3-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
35	2020	기존보수	S3-G1	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	1.50		1.50	m	1	1.80											

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결합부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량				년월	
1	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
2	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
3	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
4	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.45		0.45	m	1	0.54											
5	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
6	2020	기존보수	S4-G1	PSC BOX 내부	재료분리	0.40	3.00		1.20	m²	1	1.44											
7	2020	기존보수	S4-G1	PSC BOX 내부	재료분리	0.40	1.00		0.40	m²	1	0.48											
8	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
9	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
10	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
11	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
12	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.20		0.20	m	1	0.24											
13	2020	기존보수	S4-G1	PSC BOX 내부	재료분리	0.20	2.00		0.40	m²	1	0.48											
14	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
15	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	3.40		3.40	m	1	4.08											
16	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
17	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.40		1.40	m	1	1.68											
18	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.80		1.80	m	1	2.16											
19	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
20	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.20	8.40		8.40	m	1	10.08											
21	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	5.20		5.20	m	1	6.24											
22	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	4.70		4.70	m	1	5.64											
23	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
24	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	3.50		3.50	m	1	4.20											
25	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
26	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
27	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
28	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
29	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
30	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
31	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	3.60		3.60	m	1	4.32											
32	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
33	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
34	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
35	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	0.40		2.80	m	7	3.36											
36	2020	기존보수	S4-G1	PSC BOX 내부	철근노출	0.10	0.10		0.01	m²	1	0.01											
37	2020	기존손상	S4-G1	바닥판	균열(0.3mm미만)	0.10	3.00		3.00	m	1	3.60											
38	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.60		1.60	m	1	1.92											
39	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.10		0.10	m	1	0.12											
40	2020	기존손상	S4-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결 함 규 모						보수 물량	보수내역						결합부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
2	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.60	m	2	0.72											
3	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
4	2020	기존보수	S5-G1	PSC BOX 내부	철근노출	0.10	0.10		0.01	m²	1	0.01											
5	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
6	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	2.60		2.60	m	1	3.12											
7	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	2.00		2.00	m	1	2.40											
8	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	0.60		1.20	m	2	1.44											
9	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
10	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.10		0.10	m	1	0.12											
11	2020	기존보수	S5-G1	PSC BOX 내부	철근노출	0.80	1.50		1.20	m³	1	1.44											
12	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
13	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	3.00		3.00	m	1	3.60											
14	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	0.60		1.20	m	2	1.44											
15	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.20	0.60		0.60	m	1	0.72											
16	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.20	1.40		1.40	m	1	1.68											
17	2020	기존보수	S5-G1	배수시설	유도배수로탈락				1.00	ea	1	1.00											
18	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	8.00		8.00	m	1	9.60											
19	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
20	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.20	0.80		0.80	m	1	0.96											
21	2020	기존손상	S5-G1	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	2.50		2.50	m	1	3.00											
22	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
23	2020	기존보수	S5-G1	PSC BOX 내부	철근노출	0.10	0.10		0.01	m³	1	0.01											
24	2020	기존보수	S5-G1	PSC BOX 내부	재료분리	0.70	4.00		2.80	m³	1	3.36											
25	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
26	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
27	2020	기존손상	S5-G1	PSC BOX 내부	균열(0.3mm미만)	0.10	4.50		4.50	m	1	5.40											
28	2020	기존손상	S5-G1	바닥판	균열(0.3mm미만)	0.10	6.20		6.20	m	1	7.44											

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결합부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존보수	S3-G2	PSC BOX 내부	거푸집미제거				1.00	ea	1	1.00											
2	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
3	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	1.30		1.30	m	1	1.56											
4	2020	기존손상	S3-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	4.00		4.00	m	1	4.80											
5	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	1.60		1.60	m	1	1.92											
6	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	1.80		1.80	m	1	2.16											
7	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
8	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	2.40		2.40	m	1	2.88											
9	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
10	2020	기존손상	S3-G2	바닥판	보수부 균열(0.3mm미만)	0.15	3.60		3.60	m	1	4.32											
11	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	0.40		4.40	m	11	5.28											
12	2020	기존보수	S3-G2	PSC BOX 내부	재료분리	0.40	0.60		0.24	m²	1	0.29											
13	2020	기존손상	S3-G2	PSC BOX 내부	페콘크리트 퇴적				1.00	ea	1	1.00											
14	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
15	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
16	2020	기존손상	S3-G2	바닥판	보수부 균열(0.3mm미만)	0.10	2.00		4.00	m	2	4.80											
17	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	0.70		8.40	m	12	10.08											
18	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
19	2020	기존손상	S3-G2	바닥판	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
20	2020	기존손상	S3-G2	바닥판	보수부 균열(0.3mm미만)	0.10	2.00		2.00	m	1	2.40											
21	2020	기존손상	S3-G2	바닥판	보수부 균열(0.3mm미만)	0.10	3.00		3.00	m	1	3.60											
22	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
23	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	1.60		1.60	m	1	1.92											
24	2020	기존손상	S3-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
25	2020	기존손상	S3-G2	PSC BOX 내부	보수부 균열																		

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존손상	S4-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	5.00		5.00	m	1	6.00											
2	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.50		1.50	m	1	1.80											
3	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.10		2.20	m	2	2.64											
4	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.30		0.60	m	2	0.72											
5	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.40		1.40	m	1	1.68											
6	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
7	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
8	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
9	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
10	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
11	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
12	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
13	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
14	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
15	2020	기존손상	S4-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	2.00		2.00	m	1	2.40											
16	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	5.00		5.00	m	1	6.00											
17	2020	기존손상	S4-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
18	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
19	2020	기존손상	S4-G2	바닥판	보수부 균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
20	2020	기존손상	S4-G2	바닥판	보수부 균열(0.3mm미만)	0.10	0.60		8.40	m	14	10.08											
21	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
22	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
23	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	3.20		3.20	m	1	3.84											
24	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
25	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	2.60		2.60	m	1	3.12											

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
41	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.90		0.90	m	1	1.08											
42	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
43	2020	기존손상	S4-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	1.50		1.50	m	1	1.80											
44	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.40		4.80	m	12	5.76											
45	2020	기존손상	S4-G2	PSC BOX 내부	보수부 균열(0.3mm미만)	0.10	0.80		0.80	m	1	0.96											
46	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
47	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
48	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
49	2020	기존손상	S4-G2	바닥판	보수부 균열(0.3mm미만)	0.10	3.00		3.00	m	1	3.60											
50	2020	기존보수	S4-G2	PSC BOX 내부	망상균열(0.3mm미만)	0.50	0.70		0.35	m²	1	0.42											
51	2020	기존손상	S4-G2	바닥판	보수부 균열(0.3mm미만)	0.10	5.00		5.00	m	1	6.00											
52	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
53	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
54	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
55	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.20		0.20	m	1	0.24											
56	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
57	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
58	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.40		0.80	m	2	0.96											
59	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
60	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.80	m	2	0.96											
61	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.30		0.30	m	1	0.36											
62	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		0.60	m	1	0.72											
63	2020	기존손상	S4-G2	PSC BOX 내부	균열(0.3mm미만)	0.10	0.25		0.25	m	1	0.30											
64	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10	0.50		0.50	m	1	0.60											
65	2020	기존손상	S4-G2	바닥판	균열(0.3mm미만)	0.10																	

[illegible]

[illegible]

[illegible]

연번	적출 년도	손상 구분	위 치	부 재	결함종류	결함규모						보수 물량	보수내역						결함부 사진			외관조사 망도	비 고
						폭	길이	깊이	수량	단위	개소		1차보수내역			2차보수내역			점검	보수	점검		
													mm/m	m	mm	년월	보수공법	물량					
1	2020	기존손상	S4-G3	PSC BOX 내부	거푸집 적치				1.00	ea	1	1.00											
2	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
3	2020	기존보수	S4-G3	PSC BOX 내부	보수부 망상균열(0.3mm미만)	0.50	0.50		0.25	m²	1	0.30											
4	2020	기존보수	S4-G3	바닥판	백대	0.30	1.50		0.45	m²	1	0.54											
5	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
6	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
7	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	3.50		3.50	m	1	4.20											
8	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	0.40		5.60	m	14	6.72											
9	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	0.60		1.20	m	2	1.44											
10	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	1.10		1.10	m	1	1.32											
11	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
12	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
13	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	2.00		2.00	m	1	2.40											
14	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	1.00		2.00	m	2	2.40											
15	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	2.00		2.00	m	1	2.40											
16	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	2.20		2.20	m	1	2.64											
17	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
18	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	3.40		3.40	m	1	4.08											
19	2020	기존손상	S4-G3	PSC BOX 내부	균열(0.3mm미만)	0.10	1.00		1.00	m	1	1.20											
20	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	0.70		0.70	m	1	0.84											
21	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	0.40		4.00	m	10	4.80											
22	2020	기존손상	S4-G3	바닥판	보수부 균열(0.3mm미만)	0.10	2.50		2.50	m	1	3.00											
23	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	0.40		0.40	m	1	0.48											
24	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0.10	1.20		1.20	m	1	1.44											
25	2020	기존손상	S4-G3	바닥판	균열(0.3mm미만)	0																	

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]

[illegible]