

32. 절토사면(STA.8+920~9+650)

ID : 절토사면 (Sta. 3+550 ~ 3+660)

A258 2구간 2차시공 전경

A259 1구간 2차시공 전경 - 3구간

← 역산 방향

→ 평택 방향

A260 1구간 2차시공 전경

A265 2구간 1차시공 전경

A266 가변사면


2구간 2차시공

A261 3차시공 전경

A263 264

채움

A26K




A252 4차시공 전경

손상 현황 표

번호	구분	결함 내용	손상규모					비고
			폭(mm)	너비(m)	길이(m)	개소	손상물량	
1	배수로	측구 채우	-	0.5	5.0	1	2.50	m³ 보수
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								

KEY PLAN



분례

균열	광상균열	재료분리
편침/공동	박리, 박락/ 파손	시공이음/ 혼분리
누수/ 습윤부	백태	철근노출
편크리트 변색, 녹물	표장요철	강재부식
좌굴/변형	돌트결함	용접불량

용역명	서부내륙고속도로 2025년 시설물 정기안전점검 용역(하반기)
시설물명	절토사면(STA.8+920~9+650)
점검일시	2025. 07 ~ 2025. 12
확인자	책임기술자 김경수
도면번호	32-01


ID : 절토사면 (Sta. 3+550 ~ 3+660)

손상 현황 표

[illegible]

← 익산 방향

평택 방향 →



0257
정권계단 전

0253 정경사 42권


0254 2번 지

1255 지어 사하여 47개 지어
256 37개

KEY PLAN

← 익산

→ **열**



본	려
---	---

	균열		망상균열		재료분리
	편칭/공동		벽리, 박락/피손		시공이 충분리
	누수/ 습윤부		벽태		철근노출
	콘크리트 변색, 누출		표장오염		강재부식
	차광/변형		벌트결합		응집물

표	구	여
---	---	---

서부내륙고속도로 2025년 시설물 정기안전점검 용역(하반기)

시설물명

정토사면(STA.8+920~9+650)

점검일시

2025. 07 ~ 2025. 12

확 인 자

책임기