

43. 보강토옹벽

(STA.2+157.750~2

+287.500(R))

전경




시점부 전경



중점부 전경



전면부 전경



옹벽 상부 도로 전경








기초, 지반부 전경



옹벽 상단 사면 전경

손상현황

			
01 (25년 하반기)	전면부 블록균열(1)	01 (26년 상반기)	전면부 블록균열(1)
			
02 (25년 하반기)	전면부 블록균열(2)	02 (26년 상반기)	전면부 블록균열(2)
			
03 (25년 하반기)	전면부 블록균열(3)	03 (26년 상반기)	전면부 블록균열(3)

	
04 (25년 하반기)	04 (26년 상반기)
	
05 (25년 하반기)	05 (26년 상반기)
	
06 (25년 하반기)	06 (26년 상반기)

			
07 (25년 하반기)	웅벽 상부 도로 포장 균열	07 (26년 상반기)	웅벽 상부 도로 포장 균열
			
07 (26년 상반기)	웅벽 상부 도로 포장 균열	07 (26년 상반기)	웅벽 상부 도로 포장 균열
			
08 (25년 하반기)	기초, 지반부 상태양호	08 (26년 상반기)	기초, 지반부 상태양호