

26. 신봉교

전경



교면포장 전경



신축이음장치 전경



바닥판하면 전경



거더 전경







교대 전경






교대 전경

손상현황

			
01 (25년 하반기)	바닥판 하면 철근노출	01 (26년 상반기)	바닥판 하면 철근노출
			
02 (25년 하반기)	바닥판 하면 백태, 유공관 길이부족	02 (26년 상반기)	바닥판 하면 백태, 유공관 길이부족
			
03 (25년 하반기)	바닥판 하면 박락	03 (26년 상반기)	바닥판 하면 박락



			
04 (25년 하반기)	교대 누수오염	04 (26년 상반기)	교대 누수오염
			
05 (25년 하반기)	교대 잡철근 노출	05 (26년 상반기)	교대 잡철근 노출
			
06 (25년 하반기)	교대 망상균열(0.3mm미만)	06 (26년 상반기)	교대 망상균열(0.3mm미만)



	
07 (25년 하반기)	07 (26년 상반기)
	
08 (25년 하반기)	08 (26년 상반기)
	
09 (25년 하반기)	09 (26년 상반기)
	

	
10 (25년 하반기)	10 (26년 상반기)
	
11 (25년 하반기)	11 (26년 상반기)
	
12 (25년 하반기)	12 (26년 상반기)

교대 실란트 갈라짐	교대 실란트 갈라짐
교대 균열 (0.3mm미만)	교대 균열 (0.3mm미만)
교대 균열 (0.3mm미만)	교대 균열 (0.3mm미만)

			
13 (25년 하반기)	교면포장 아스콘 망상균열	13 (26년 상반기)	교면포장 아스콘 망상균열
			
14 (25년 하반기)	교면포장 아스콘 균열	14 (26년 상반기)	교면포장 아스콘 균열
			
15 (25년 하반기)	교면포장 아스콘 패임	15 (26년 상반기)	교면포장 아스콘 패임

	
16 (25년 하반기)	16 (26년 상반기)
신축이음 후타재 균열 (0.3mm미만)	신축이음 후타재 균열 (0.3mm미만)
	
17 (25년 하반기)	17 (26년 상반기)
신축이음 후타재 균열 (0.3mm미만)	신축이음 후타재 균열 (0.3mm미만)
18 (25년 하반기)	18 (26년 상반기)
신축이음 후타재 파손	신축이음 후타재 파손

	
19 (25년 하반기)	19 (26년 상반기)
	
20 (25년 하반기)	20 (26년 상반기)
	
21 (25년 하반기)	21 (26년 상반기)

신축이음
유간 토사퇴적


신축이음
유간 토사퇴적

배수시설
배수구 막힘

배수시설
배수구 막힘

방호벽
균열 (0.3mm미만)

방호벽
균열 (0.3mm미만)

	
22 (25년 하반기)	22 (26년 상반기)
방호벽 균열 (0.3mm 이상)	방호벽 균열 (0.3mm 이상)
	
23 (25년 하반기)	23 (26년 상반기)
방호벽 철근노출	방호벽 철근노출
	
24 (26년 상반기)	25 (26년 상반기)
거더 정착구 누유흔적	거더 정착구 누유흔적

