




3. 신축이음 전수조사

□ 장천교 신축이음장치 점검결과

위 치	점 검 결 과				
J1 (A1)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:2.0cm	전경	일평균기온:23.2℃ 하부유간:9.0cm	
J2 (P2)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:3.5cm	전경	일평균기온:23.2℃ 하부유간:5.5cm	
J3 (P4)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:4.3cm	전경	일평균기온:23.2℃ 하부유간:8.0cm	
J4 (P7)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:6.6cm	전경	일평균기온:23.2℃ 하부유간:11.0cm	
J5 (P10)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:6.8cm	전경	일평균기온:23.2℃ 하부유간:10.0cm	

위 치	점 검 결 과				
J6 (P13)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:7.6cm	전경	일평균기온:23.2℃ 하부유간:7.5cm	
J7 (P15)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:3.0cm	전경	일평균기온:23.2℃ 하부유간:5.4cm	
J8 (A2)	1	2	3	4	5
					
	전경	일평균기온:23.2℃ 신축이음유간:2.6cm	전경	일평균기온:23.2℃ 하부유간:3.0cm	