

동탄신리배수지 송수관로

					
송수-1(Sta.1+0.0)	매설환경	상태양호	송수-1(Sta.28+0.0)	포장 및 지반	상태양호
					
송수-1(Sta.21+0.00)	포장 및 지반	상태양호	송수-1(Sta.21+0.00)	포장 및 지반	상태양호
					
송수-1(Sta.80+00.0)	화성동탄(2) 택지개발사업 조성공사 구간	상태양호	송수-1(Sta.118+00.0)	화성동탄(2) 택지개발사업 조성공사 구간	상태양호
					
송수-2(Sta.118+2.0)	포장 및 지반	상태양호	송수-2(Sta.128+0.0)	포장 및 지반	상태양호



송수-2(Sta.134+18.0)

포장 및 지반 상태양호



송수-2(Sta.137+10.0)

포장 및 지반 상태양호



송수-2(Sta.118+2.0)

포장 및 지반 상태양호



송수-2(Sta.128+0.0)

포장 및 지반 상태양호



송수-2(Sta.118+2.0)

포장 및 지반 상태양호



송수-2(Sta.128+0.0)

포장 및 지반 상태양호



송수1 Sta.1+0.00(제수)

침수(H=2.5m)



송수1 Sta.1+0.00(점검구실)

출입구 콘크리트 박리



송수1 Sta.22+0.00(공기)

출입구 콘크리트 박리



송수1 Sta.46+16.00(이토)

출입구 철근노출 및 열화



송수1 Sta.66+1.00(공기)

밸브 및 구조물 상태양호



송수1 Sta.116+15.0(제수)

밸브실 침수(H=2.0m)



송수1 Sta.116+15.00(제수)	출입구 보호콘크리트 박리
-----------------------	------------------



송수2 Sta.140+0.00(점검구실)	구조물 및 마개 상태양호
---------------------------	------------------



송수3 Sta.11+15.3(공기)	출입구 백태 발생
---------------------	-----------



송수3 Sta.41+17.3(이토)	밸브실 침수(H=4.5m)
---------------------	----------------



공기밸브실	사다리 설치 상태양호
-------	-------------



점검구실	사다리 설치 상태양호
------	-------------



제수밸브실

사다리 설치 상태양호



공기밸브실

사다리 설치 상태양호



공기밸브실

맨홀 덮개 상태양호



이토밸브실

맨홀 덮개 상태양호



점검구실

맨홀 덮개 상태양호



공기밸브실

맨홀 덮개 상태양호

