



REPORT OF ULTRASONIC EXAMINATION 초음파비파괴검사보고서				INDT		보고서번호 Report No.	ISU- 151102 - K08 -10
경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348				國際非破壞検査(株)		페이지 Page	1 of 9
Customer 주문주/Const. & MFR. 제작자 (주)신대구부산고속도로 / (주)아워브레인		Project Name 공사명 신대구부산고속도로 1구간 정밀안전진단용역		Location 검사위치 청도2교			
Item Name 제품명 Steel Box Girder		Material 재질 / Thickness 두께 SM490 / 8-32mm		Dwg. No. 도면번호 N/A			
Joint Config. 용접모양 ☐ Bevel Groove ☐ V-Groove ☐ K-Groove ☒ X-Groove ☐		Code 규격 / Procedure 절차서 KS B 0896 2류 (L검출레벨) INDT-QCP-UT-01K		Surface Condition 표면상태 ☒ As Welded ☐ As Forged ☐ As Cast ☐ As ground ☐			
Testing Equipment 검사장비 Sonatest Sitiescan140 (1401238C) Due Date (유효기간) : 2015.12.07		Linearity 직선성 Amplitude Control Screen Height Within $\pm 2\%$ FSH Within $\pm 1\%$ FSH		Scanning Sensitivity 탐상감도 STB-A2 $\varnothing 4 \times 4$ hole 80% +6 dB			
Method 검사방법 ☒ Contact 접촉법 ☐ Immerse 수침법		Couplant 접촉매질 ☐ Glycerin ☐ Oil ☒ C.M.C ☐		Calibration Block 교정블럭 STB-A1,A2 Block			
Transducer 탐촉자	Model 모델	Serial No. 일련번호	Angle 교정각도(°)	Frequency 주파수(MHz)	Size 크기(mm)	Cable 케이블	
	KUB70-4	F001	70	4	8×9	LEMO	
 							
Memo 메모							
Examined by 시험자 장동현			기능사 기술자		Date of Examination 시험일자 2015년 8월 31일 ~ 2015년 10월 22일		
Approved by 승인자 봉경득			기사 책임기술자		☐ Witnessed by ☐ Reviewed by		

REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

國際非破壞検査(株)

보고서번호
Report No.

ISU- 151102 - K08 -10

페이지
Page

2 of 9

확인번호 Ident No.	합 Acc ept	불 Rej ect	위치 Location (X)	길이 Length (L)	위치 Location (Y)	깊이 Depth (D)	보정곡선 DAC (max)	등급 Grade	용접사 Welder	비고 Remarks
1	대구 G1-UT1	✓		NO RECORDABLE INDICATION				1		
2	UT2	✓		NO RECORDABLE INDICATION				1		
3	UT3	✓		NO RECORDABLE INDICATION				1		
4	UT4	✓		NO RECORDABLE INDICATION				1		
5	UT5	✓		NO RECORDABLE INDICATION				1		
6	UT6	✓		NO RECORDABLE INDICATION				1		
7	UT7	✓		NO RECORDABLE INDICATION				1		
8	UT8	✓		NO RECORDABLE INDICATION				1		
9	UT9	✓		NO RECORDABLE INDICATION				1		
10	UT10	✓		NO RECORDABLE INDICATION				1		
11	UT11	✓		NO RECORDABLE INDICATION				1		
12	UT12	✓		NO RECORDABLE INDICATION				1		
13	UT13	✓		NO RECORDABLE INDICATION				1		
14	UT14	✓		NO RECORDABLE INDICATION				1		
15	UT15	✓		NO RECORDABLE INDICATION				1		
16	UT16	✓		NO RECORDABLE INDICATION				1		
17	UT17	✓		NO RECORDABLE INDICATION				1		
18	UT18	✓		NO RECORDABLE INDICATION				1		
19	UT19	✓		NO RECORDABLE INDICATION				1		
20	UT20	✓		NO RECORDABLE INDICATION				1		
21	UT21	✓		NO RECORDABLE INDICATION				1		
22	UT22	✓		NO RECORDABLE INDICATION				1		
23	대구 G2-UT1	✓		NO RECORDABLE INDICATION				1		
24	UT2	✓		NO RECORDABLE INDICATION				1		
25	UT3	✓		NO RECORDABLE INDICATION				1		
26	UT4	✓		NO RECORDABLE INDICATION				1		
27	UT5	✓		NO RECORDABLE INDICATION				1		
28	UT6	✓		NO RECORDABLE INDICATION				1		
29	UT7	✓		NO RECORDABLE INDICATION				1		
30	UT8	✓		NO RECORDABLE INDICATION				1		

REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

보고서번호
Report No.

ISU- 151102 - K08 -10

페이지
Page

3 of 9

國際非破壞検査(株)

확인번호 Ident No.	합 Acc ept	불 Rej ect	위치 Location (X)	길이 Length (L)	위치 Location (Y)	깊이 Depth (D)	보정곡선 DAC (max)	등급 Grade	용접사 Welder	비고 Remarks
31	대구 G2-UT9	✓		NO RECORDABLE INDICATION				1		
32	UT10	✓		NO RECORDABLE INDICATION				1		
33	UT11	✓		NO RECORDABLE INDICATION				1		
34	UT12	✓		NO RECORDABLE INDICATION				1		
35	UT13	✓		NO RECORDABLE INDICATION				1		
36	UT14	✓		NO RECORDABLE INDICATION				1		
37	UT15	✓		NO RECORDABLE INDICATION				1		
38	UT16	✓		NO RECORDABLE INDICATION				1		
39	UT17	✓		NO RECORDABLE INDICATION				1		
40	UT18	✓		NO RECORDABLE INDICATION				1		
41	UT19	✓		NO RECORDABLE INDICATION				1		
42	UT20	✓		NO RECORDABLE INDICATION				1		
43	UT21	✓		NO RECORDABLE INDICATION				1		
44	UT22	✓		NO RECORDABLE INDICATION				1		
45	부산 G1-UT1	✓		NO RECORDABLE INDICATION				1		
46	UT2	✓		NO RECORDABLE INDICATION				1		
47	UT3	✓		NO RECORDABLE INDICATION				1		
48	UT4	✓		NO RECORDABLE INDICATION				1		
49	UT5	✓		NO RECORDABLE INDICATION				1		
50	UT6	✓		NO RECORDABLE INDICATION				1		
51	UT7	✓		NO RECORDABLE INDICATION				1		
52	UT8	✓		NO RECORDABLE INDICATION				1		
53	UT9	✓		NO RECORDABLE INDICATION				1		
54	UT10	✓		NO RECORDABLE INDICATION				1		
55	UT11	✓		NO RECORDABLE INDICATION				1		
56	UT12	✓		NO RECORDABLE INDICATION				1		
57	UT13	✓		NO RECORDABLE INDICATION				1		
58	UT14	✓		NO RECORDABLE INDICATION				1		
59	UT15	✓		NO RECORDABLE INDICATION				1		
60	UT16	✓		NO RECORDABLE INDICATION				1		

REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

國際非破壞検査(株)

보고서번호

Report No.

ISU- 151102 - K08 -10


페이지

Page


4 of 9


확인번호 Ident No.	합 Acc ept	불 Rej ect	위치 Location (X)	길이 Length (L)	위치 Location (Y)	깊이 Depth (D)	보정곡선 DAC (max)	등급 Grade	용접사 Welder	비고 Remarks
61			부산 G1-UT17	✓		NO RECORDABLE INDICATION		1		
62			UT18	✓		NO RECORDABLE INDICATION		1		
63			UT19	✓		NO RECORDABLE INDICATION		1		
64			UT20	✓		NO RECORDABLE INDICATION		1		
65			UT21	✓		NO RECORDABLE INDICATION		1		
66			UT22	✓		NO RECORDABLE INDICATION		1		
67			부산 G2-UT1	✓		NO RECORDABLE INDICATION		1		
68			UT2	✓		NO RECORDABLE INDICATION		1		
69			UT3	✓		NO RECORDABLE INDICATION		1		
70			UT4	✓		NO RECORDABLE INDICATION		1		
71			UT5	✓		NO RECORDABLE INDICATION		1		
72			UT6	✓		NO RECORDABLE INDICATION		1		
73			UT7	✓		NO RECORDABLE INDICATION		1		
74			UT8	✓		NO RECORDABLE INDICATION		1		
75			UT9	✓		NO RECORDABLE INDICATION		1		
76			UT10	✓		NO RECORDABLE INDICATION		1		
77			UT11	✓		NO RECORDABLE INDICATION		1		
78			UT12	✓		NO RECORDABLE INDICATION		1		
79			UT13	✓		NO RECORDABLE INDICATION		1		
80			UT14	✓		NO RECORDABLE INDICATION		1		
81			UT15	✓		NO RECORDABLE INDICATION		1		
82			UT16	✓		NO RECORDABLE INDICATION		1		
83			UT17	✓		NO RECORDABLE INDICATION		1		
84			UT18	✓		NO RECORDABLE INDICATION		1		
85			UT19	✓		NO RECORDABLE INDICATION		1		
86			UT20	✓		NO RECORDABLE INDICATION		1		
87			UT21	✓		NO RECORDABLE INDICATION		1		
88			UT22	✓		NO RECORDABLE INDICATION		1		
			~ B L A N K ~							

대구 G1



대구 G2





REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

國際非破壞検査(株)

보고서번호
Report No.
페이지
Page

ISU- 151102 - K08 -10

7 of 9



REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

國際非破壞検査(株)

보고서번호

Report No.

페이지

Page

ISU- 151102 - K08 -10

8 of 9



REPORT OF ULTRASONIC EXAMINATION

초음파비파괴검사보고서

경기도 광명시 오리로 349 (소하동) T:02)897-5859 F:02)897-5348

INDT

國際非破壞検査(株)

보고서번호
























Report No.

페이지

Page

ISU- 151102 - K08 -10

9 of 9

61	62	63	64	65
				
66	67	68	69	70
				
71	72	73	74	75
				
76	77	78	79	80
				
81	82	83	84	85
				
86	87	88		
			N/A	N/A