


신 진 교

바닥판 상면 손상현황도

P1 ~ A2(S2)



KEY PLAN

장안리 ←



→ 삼합리


범례



삼합리



③ 유간부 토사퇴적 L=13.0 ④ 후타재 균열 0.1/0.2x10ea



A2



6/6

② 포장 패임 0.2x13.0

5/6

① 0.2/0.5x30ea

4/6


3/6

2/6

1/6

0

P1



4 5



장안리