

[오송2교(T2)] [PSC Box교 구간] 결과표

개별교량명 오송2교(T2)													
부재의 분류		상부구조		2차부재	기타부재				받침	하부구조		내구성 요소	
번호	구조형식	바닥판	거더	가로보	궤도부	배수시설	난간, 연석, 보도부	신축이음	교량받침	하부	기초	탄산화(상)	탄산화(하)
S5-1	PSC Box	a	b	N/A	N/A	a	a	a	a	c	Q	N/A	N/A
S5-2	PSC Box	a	b	N/A	N/A	a	a	a	a	c	Q	N/A	N/A
S6-1	PSC Box	b	b	N/A	N/A	c	a	N/A	a	c	Q	N/A	N/A
S6-2	PSC Box	c	b	N/A	N/A	c	a	c	c	c	Q	N/A	N/A
S7-1	PSC Box	a	b	N/A	N/A	a	a	N/A	a	c	Q	N/A	N/A
S7-2	PSC Box	a	b	N/A	N/A	a	a	N/A	a	b	Q	N/A	N/A
S7-3	PSC Box	b	b	N/A	N/A	c	a	a	a	b	Q	N/A	N/A
S8-1	PSC Box	a	b	N/A	N/A	a	a	N/A	a	b	Q	N/A	N/A
S8-2	PSC Box	a	b	N/A	N/A	a	a	N/A	a	c	Q	N/A	N/A
S8-3	PSC Box	a	b	N/A	N/A	a	c	a	a	b	Q	N/A	N/A
S15	PSC Box	b	b	N/A	N/A	c	a	a	a	b	Q	N/A	N/A
S19	PSC Box	b	b	N/A	N/A	c	a	a	a	b	Q	N/A	N/A
S20	PSC Box	b	b	N/A	N/A	a	c	a	a	a	Q	N/A	N/A
S21	PSC Box	b	b	N/A	N/A	a	a	a	a	a	Q	N/A	N/A
S22	PSC Box	b	b	N/A	N/A	a	b	N/A	N/A	N/A	Q	N/A	N/A
평균		0.167	0.200	N/A	N/A	0.200	0.147	0.133	0.121	0.271	N/A	N/A	N/A
가중치		27	23	N/A	N/A	3	2	9	9	20	N/A	N/A	N/A
(평균X가중치)/가중치합		0.045	0.046	N/A	N/A	0.006	0.003	0.012	0.011	0.054	N/A	N/A	N/A
1. 환산결함도 점수 =												0.177	
2. 상태평가 결과 =												b	

[오송2교(상)] [Rahmen교 구간] 결과표

개별교량명 오송2교(T2)													
부재의 분류		상부구조		2차부재	기타부재				받침	하부구조		내구성 요소	
번호	구조형식	바닥판	거더	가로보	궤도부	배수시설	난간, 연석, 보도부	신축이음	교량받침	하부	기초	탄산화(상)	탄산화(하)
S9-1	PSC Box	a	c	a	N/A	a	b	N/A	N/A	a	Q	N/A	N/A
S9-2	PSC Box	a	c	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S9-3	PSC Box	a	c	a	N/A	a	a	a	a	a	Q	N/A	N/A
S10-1	PSC Box	a	c	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S10-2	PSC Box	a	c	a	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S10-3	PSC Box	a	c	b	N/A	a	a	a	a	a	Q	N/A	N/A
S11-1	PSC Box	a	c	b	N/A	a	b	N/A	N/A	b	Q	N/A	N/A
S11-2	PSC Box	a	b	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S11-3	PSC Box	a	c	b	N/A	a	a	a	a	a	Q	N/A	N/A
S12-1	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S12-2	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S12-3	PSC Box	b	a	b	N/A	a	a	a	a	a	Q	N/A	N/A
S13-1	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S13-2	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S13-3	PSC Box	b	c	b	N/A	a	a	a	a	a	Q	N/A	N/A
S14-1	PSC Box	b	c	b	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S14-2	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S14-3	PSC Box	b	c	b	N/A	a	a	a	a	b	Q	N/A	N/A
S16-1	PSC Box	b	c	b	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S16-2	PSC Box	b	c	b	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S16-3	PSC Box	b	c	b	N/A	a	a	a	a	b	Q	N/A	N/A
S17-1	PSC Box	b	c	b	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S17-2	PSC Box	b	c	b	N/A	a	a	N/A	N/A	a	Q	N/A	N/A
S17-3	PSC Box	b	a	b	N/A	a	a	a	a	b	Q	N/A	N/A
S18-1	PSC Box	a	c	b	N/A	a	a	N/A	N/A	c	Q	N/A	N/A
S18-2	PSC Box	a	c	b	N/A	a	a	N/A	N/A	b	Q	N/A	N/A
S18-3	PSC Box	b	c	b	N/A	a	a	N/A	N/A	c	Q	N/A	N/A
S18-4	PSC Box	a	c	b	N/A	a	c	a	a	c	Q	N/A	N/A
평균		0.157	0.371	0.182	N/A	0.100	0.118	0.100	0.100	0.164	N/A	N/A	N/A
가중치		27	21	5	N/A	3	2	3	3	29	N/A	N/A	N/A
(평균X가중치)/가중치합		0.042	0.078	0.009	N/A	0.003	0.002	0.003	0.003	0.048	N/A	N/A	N/A
1. 환산결함도 점수 =												0.189	
2. 상태평가 결과 =												b	

[오송2교 PSCB구간] 결과표

개별교량명 :		오송2교(T2)				
구분	구조형식	환산 결함도점수	상태평가 결과	연장(m)	연장비	환산결함도점수 X 연장비
본 교	PSC Box교	0.177	b	456	1.000	0.177
합계(Σ)		0	0	456	1.000	0.177
<평가자 의견>						
1. 환산결함도 점수 =						0.177
2. 상태평가 결과 =						b

[오송2교 Rahmen구간] 결과표

개별교량명 :		오송2교(T2)				
구분	구조형식	환산 결함도점수	상태평가 결과	연장(m)	연장비	환산결함도점수 X 연장비
본 교	Rahmen교	0.189	b	448	1.000	0.189
합계(Σ)		0	0	448	1.000	0.189
<평가자 의견>						
1. 환산결함도 점수 =						0.189
2. 상태평가 결과 =						b

[오송2교(T2)] 결과표

교 량 명 : 오송2교(T2)						
종류	구분	환산 결함도점수	상태평가 등급	연장 (M)	연장비	환산결함도점수 X 연장비
PSCB-Girder + Rahmen 교량	본교	0.177	b	456	0.504	0.089
		0.189	b	448	0.496	0.094
합계(Σ)				904	1.000	0.183
<평가자 의견>						
1. 평가지수 =						0.183
2. 상태평가 결과 =						B