




29. 한 교 천 교 (B43)



위치	21 SPAN -2	선별	T1	부위	TCL
내용	균열	Cw= 0.2/0.4			




위치	24 SPAN -1	선별	T1	부위	TCL
내용	균열	Cw= 0.2/0.4			




위치	26 SPAN -3	선별	T1	부위	TCL
내용	균열	Cw= 0.1/0.5			









위치	26 SPAN -4	선별	T1	부위	TCL
내용	균열	Cw= 0.2/0.4			







위치	26 SPAN -6	선별	T1	부위	TCL
내용	균열	Cw= 0.2/0.4			



위치	13 SPAN -6	선별	T1	부위	TCL
내용	균열	Cw= 0.3/0.2			

											
위치	15 SPAN -6	선별	T2	부위	TCL	위치	16 SPAN -1	선별	T2	부위	TCL
내용	균열	Cw= 0.1/0.4				내용	균열	Cw= 0.3/0.4			
											
위치	16 SPAN -3	선별	T2	부위	TCL	위치	17 SPAN -3	선별	T2	부위	TCL
내용	균열	Cw= 0.2X0.2				내용	균열	Cw=0.3/0.3			
											
위치	18 SPAN -3	선별	T2	부위	TCL	위치	18 SPAN -4	선별	T2	부위	TCL
내용	균열	Cw= 0.1/0.4				내용	균열	Cw= 0.1/0.4			


											
위치	18 SPAN -4	선별	T2	부위	TCL	위치	19 SPAN -1	선별	T2	부위	TCL
내용	균열	Cw= 0.1/0.4				내용	균열	Cw= 0.1/0.4			
											
위치	21 SPAN -3	선별	T2	부위	TCL	위치	21 SPAN -4	선별	T2	부위	TCL
내용	균열	Cw= 0.2/0.2				내용	균열	Cw= 0.2/0.4			
											
위치	23 SPAN -5	선별	T2	부위	침목	위치	19 SPAN -5	선별	T2	부위	TCL
내용	경계부 균열	Cw= 0.3/2.3				내용	망상균열	A= 0.4X0.2			



위치	26 SPAN -3	선별	T1	부위	TCL
내용	망상균열	A= 0.3X0.6			



위치	3 SPAN -4	선별	T2	부위	TCL
내용	침목도상분리	A= 0.3X0.6			



위치	2 SPAN -4	선별	T2	부위	TCL
내용	파손	A= 0.1X0.1			



위치	3 SPAN -2	선별	T1	부위	TCL
내용	파손	A= 0.2X0.1			



위치	3 SPAN -2	선별	T1	부위	TCL
내용	파손	A= 0.3X0.2			



위치	10 SPAN -1	선별	T1	부위	TCL
내용	표면열화	A= 1.5X3.0			




위치	12 SPAN -3	선별	T2	부위	TCL
내용	파손	A= 0.6X0.1			



위치	12 SPAN -3	선별	T2	부위	TCL
내용	재료분리	A= 0.1X0.5			




위치	13 SPAN -1	선별	T1	부위	TCL
내용	박락	A= 0.4X0.4			



위치	21 SPAN -5	선별	T1	부위	PCL
내용	파손	A= 0.1X0.3			



위치	26 SPAN -4	선별	T2	부위	TCL
내용	재료분리	A= 0.3X4.0			



위치		선별		부위	
내용					