

호남고속전환풍고가_93(17.517~17.525, S17-3)

17K517

17K520

17K525

17 SPAN - 3

TCL상면
TCL측면

TM,262.4

TM,223.4

1

2

3

4

5

6

7

8

9

10

11

12

13

① 16.0.1/0.3

② 16.0.1/0.4

TCL상면
TCL측면

TM,094.3

TM,224.2

1

2

3

4

5

6

7

8

9

10

11

12

13

③ 16.0.1/0.8

④ 15.0.1/0.4

⑤ 15.0.1/0.4

⑥ 15.0.1/0.4

⑦ 15.0.2/0.4

PCL상면

PCL상면

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.1 mm	0.4 m		56					
2	균열 0.1 mm	0.4 m		57					
3	균열 0.1 mm	0.4 m		58					
4	균열 0.1 mm	0.4 m		59					
5	균열 0.2 mm	0.4 m		60					
6	균열 0.1 mm	0.4 m		61					
7	균열 0.1 mm	0.3 m		62					
8	균열 0.1 mm	0.8 m		63					
9	균열 0.1 mm	0.3 m		64					
10	균열 0.1 mm	0.3 m		65					
11				66					
12				67					
13				68					
14				69					
15				70					
16				71					
17				72					
18				73					
19				74					
20				75					
21				76					
22				77					
23				78					
24				79					
25				80					
26				81					
27				82					
28				83					
29				84					
30				85					
31				86					
32				87					
33				88					
34				89					
35				90					
36				91					
37				92					
38				93					
39				94					
40				95					
41				96					
42				97					
43				98					
44				99					
45				100					
46				101					
47				102					
48				103					
49				104					
50				105					
51				106					
52				107					
53				108					
54				109					
55				110					

[illegible]