

호남고속선 화물고가 _104(17.604~17.613, S19-4)

17K604

17K610

17K613

19 SPAN - 4

The diagram illustrates the cross-section of a 19-span bridge deck. It is divided into three main sections: BCL상면 (Top Left), TCL상면 (Top Right), and BCL상면 (Bottom Left). The central section, labeled TM.237.1 and TM.104.4, shows 13 numbered lanes (1-13) with dimensions for lane widths and overall deck widths. The side sections, labeled TM.266.1 and TM.096.4, show 13 numbered lanes (1-13) with dimensions for lane widths and overall deck widths. The diagram includes various dimension lines and labels for different parts of the bridge deck, such as lanes, shoulders, and overall widths.

연번	손상	폭	연장	비고	연번	손상	폭	연장	비고
1	균열 0.2	mm 0.4	m		56				
2	관개부 균열 0.2	mm 0.3	m		57				
3	관개부 균열 0.2	mm 0.3	m		58				
4	관개부 균열 0.2	mm 0.3	m		59				
5	관개부 균열 0.2	mm 0.3	m		60				
6	균열 0.1	mm 0.3	m		61				
7	관개부 균열 0.2	mm 0.3	m		62				
8	관개부 균열 0.2	mm 0.4	m		63				
9	균열 0.2	mm 1.1	m		64				
10	균열 0.2	mm 0.3	m		65				
11	균열 0.2	mm 0.4	m		66				
12	균열 0.2	mm 0.6	m		67				
13	균열 0.2	mm 0.4	m		68				
14	균열 0.2	mm 0.4	m		69				
15	균열 0.2	mm 1.0	m		70				
16	균열 0.1	mm 0.4	m		71				
17	균열 0.2	mm 0.6	m		72				
18	균열 0.2	mm 0.4	m		73				
19	균열 0.2	mm 0.6	m		74				
20	균열 0.2	mm 0.6	m		75				
21	균열 0.2	mm 0.6	m		76				
22	균열 0.2	mm 0.4	m		77				
23	균열 0.2	mm 0.4	m		78				
24	균열 0.1	mm 0.4	m		79				
25	균열 0.2	mm 0.4	m		80				
26	균열 0.2	mm 0.4	m		81				
27	균열 0.2	mm 0.4	m		82				
28	균열 0.2	mm 0.4	m		83				
29	균열 0.2	mm 0.4	m		84				
30	균열 0.2	mm 0.4	m		85				
31	균열 0.2	mm 0.4	m		86				
32	균열 0.2	mm 0.3	m		87				
33	균열 0.2	mm 0.4	m		88				
34	균열 0.2	mm 0.2	m		89				
35	균열 0.1	mm 0.4	m		90				
36	관개부 균열 0.1	mm 0.4	m		91				
37	관개부 균열 0.1	mm 0.3	m		92				
38	균열 0.1	mm 0.3	m		93				
39	균열 0.1	mm 0.3	m		94				
40	균열 0.2	mm 0.4	m		95				
41	균열 0.2	mm 0.3	m		96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행 사	용 어 명	용 어 사	인 지		구 간	
				개 관 비 인 지	장 분 이 별 비 인 지		
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검운영	(국) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 부 영 강 원 강 김 경 기 문 은 작 기	연 락		
					〰 (0.3mm이하 : 흑색)	창목도상본리	
					〰 (0.3mm초과 0.5mm이하 : 황색)	망상	철타노출
					〰 (0.5mm초과 1.0mm미만 : 적색)	바리,바락,파손	누수,슬럼부
					- - - - - (1.0mm이상 : 분홍색)	백태	시공이음본리,총본리
					1200	25g	