

호남고속선 박산고가 _94(22.337~22.342km, 점속부)

A2

22K337

22K340

22K342

PCL상표

TCL 集团	TCL 集团
--------	--------

15.0	(3)
------	-----

TM.082.42

TCL 20	TCL 21
--------	--------

PCL상면

TCL	TCL
TCL상	TCL상

TM.241.1

09

30.4

21

TCL 상	TCL
TCL	TCL

PCL 상용

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.2 mm	0.4 m		56				
2	경계부 균열	0.2 mm	0.3 m		57				
3	균열	0.2 mm	0.3 m		58				
4	균열	0.2 mm	0.4 m		59				
5	균열	0.2 mm	0.4 m		60				
6	균열	0.1 mm	0.3 m		61				
7	균열	0.1 mm	0.4 m		62				
8	균열	0.1 mm	0.4 m		63				
9	균열	0.1 mm	0.4 m		64				
10	균열	0.1 mm	0.4 m		65				
11					66				
12					67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	여	용	여	사	간									
								과	인	장	아	지					
KORAIL KOREA RAILROAD	한국철도공사	2017년도	호남고속선	오송-광주승정간	콘크리트케도	점검용역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이복영	간원강 김경기 문은석	점	0220	(0.3m이하 : 목책)		천문도강방리		재로방리	
											0420	(0.3m초과 0.5m이하 : 광책)		영상		철근노출	
											0620	(0.5m초과 1.0m미만 : 목책)		박리, 박라, 파손		누수수온부	
											1020	(1.0m이상 : 통책)		변대		시공이음판리, 종판리	