

한남고속선 공주고가_부분선_18(43.765~43.771km, S17)

Figure 1 illustrates the schematic diagrams of the 15.0.1/0.4 and 16.0.1/0.7 transmission line systems. The figure is divided into two main sections: the left section for the 15.0.1/0.4 system and the right section for the 16.0.1/0.7 system. Each section contains a top part showing the transmission line layout with numbered boxes (1-10) and a bottom part showing the corresponding transmission line parameters (TM 046.4, TM 271.2, TM 273.4, TM 100.2). The top part of each section shows a series of boxes connected by lines, with some boxes labeled with numbers 1 through 10. The bottom part shows the transmission line parameters for each box, including the transmission line number (TM) and the transmission line type (PCL, TCL, TOL).

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		56				
2	균열	0.1 mm	0.7 m		57				
3	균열	0.1 mm	0.4 m		58				
4	균열	0.2 mm	0.3 m		59				
5	균열	0.1 mm	0.7 m		60				
6	균열	0.1 mm	0.7 m		61				
7	균열	0.1 mm	0.4 m		62				
8	균열	0.1 mm	0.7 m		63				
9	균열	0.1 mm	0.4 m		64				
10	균열	0.1 mm	0.7 m		65				
11	균열	0.1 mm	0.7 m		66				
12	균열	0.1 mm	0.4 m		67				
13	균열	0.1 mm	0.3 m		68				
14	균열	0.1 mm	0.4 m		69				
15	균열	0.1 mm	0.7 m		70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	여	명	용	여	사	인		견				
									과 업	안 정		장 소	인 원		
KORAIL KOREA RAILROAD	한국철도공사	한국의료대공사	2017년도 호남고속선 오송-광주승강간 콘크리트케도 점검공역			(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원		이 복 영	간 원 강 김 경 기 윤 은 석	구 간	 0.220 (0.3m이하 : 흑색)	현목도상본리		재료본리	
											 0.420 (0.3m초과 0.5m이하 : 황색)	양성		철타출	
											 0.620 (0.5m초과 1.0m이하 : 적색)	바리, 바락, 파손		부수습은부	
											 1.020 (1.0m이상 : 분홍색)	백태		시공이음본리, 종본리	
												양성		시공이음본리, 종본리	
												양성		시공이음본리, 종본리	