


호남고속선 호암교_71(46.809~46.816km, S14-5)

P14

46K816

14 SPAN - 5

46K809



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		56				
2	균열	0.1 mm	0.3 m		57				
3	균열	0.1 mm	0.4 m		58				
4	장계부 균열	0.3 mm	0.3 m		59				
5	균열	0.1 mm	0.4 m		60				
6	장계부 균열	0.3 mm	0.3 m		61				
7	균열	0.1 mm	0.3 m		62				
8	균열	0.1 mm	0.4 m		63				
9	장계부 균열	0.3 mm	0.3 m		64				
10	균열	0.1 mm	0.3 m		65				
11	균열	0.3 mm	0.3 m		66				
12	균열	0.1 mm	0.4 m		67				
13	균열	0.1 mm	0.3 m		68				
14	균열	0.1 mm	0.4 m		69				
15	균열	0.1 mm	0.3 m		70				
16	백막(반장)	1.4 m	0.4 m		71				
17	균열	0.1 mm	0.7 m		72				
18	균열	0.1 mm	0.7 m		73				
19	균열	0.1 mm	0.7 m		74				
20	균열	0.1 mm	0.7 m		75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시행사	영업역명	영업역사	관리인원		구간	구간구분	구간구분	구간구분									
			개업책임자	관리인원													
KORAIL 한국철도공사 KOREA RAILROAD	2017년도 호남고속선 오송-광주승정간 콘크리트캐드 점검용역	(주)한국구조물안전연구원 (주)한국국토안전연구원 (재)한국건설품질연구원	이복영	김윤강 김경기 문은석	연평												
																	
																	
																	