


호남고속선 호암교_113(47.103~47.110km, S23-2)

47K103

47K110

23SPAN - 2



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.2	mm 0.4	m		56				
2	균열 0.2	mm 0.4	m		57				
3	균열 0.1	mm 0.7	m		58				
4	균열 0.1	mm 0.4	m		59				
5	균열 0.1	mm 0.4	m		60				
6					61				
7					62				
8					63				
9					64				
10					65				
11					66				
12					67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

	시행사	한국철도공사	2017년도 호남고속선 오송-광주승정간 편크리트케도 점검용역	용역명	용역사	이 박 영		용역		0220 (0.3mm이하 : 흑색)		한목도상문리		재료문리															
						과업책임자	관리책임자										0420 (0.3mm초과 0.5mm이하 : 황색)		양상		철근도출								
						간원강	관리책임자																	0620 (0.5mm초과 1.0mm이하 : 적색)		바닥,벽면,표선		부수,승인부	
						김정기	관리책임자																						