

호남고속선 호암교-105(47.047~47.054km, S21-4)

47K047

47K054
21 SPAN - 4

21 SPAN - 4

[illegible]

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1	0.7		56				
2	파손	0.3	0.2	산구	57				
3					58				
4					59				
5					60				
6					61				
7					62				
8					63				
9					64				
10					65				
11					66				
12					67				
13					68				
14					69				
15					70				
16					71				
17					72				
18					73				
19					74				
20					75				
21					76				
22					77				
23					78				
24					79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54					109				
55					110				

시	행	사	용	역	영	사	건		용				
							과 업 내 지	장 소 내 지					
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트케도 점검용역	(주) 한국구조물안전연구원 (주) 한국도로안전연구원 (재) 한국건설품질연구원	이 복 영	간 원 강 김 경 기 문 준 기	영원		02220 (0.3mm이하 : 흑색)		재료보리			
								04220 (0.3mm초과 0.5mm이하 : 황색)		명상		철근노출	
								06220 (0.5mm초과 1.0mm이하 : 적색)		바리, 바라, 파손		누수 습윤 부	
								10220 (1.0mm이상 : 분홍색)		변태		시공이음보리, 종보리	