


호남고속선 서편교_10(47.943~47.950km, S2-4)

47K943

47K950

2 SPAN - 4



(아) (아)

(아호)

TCL상대	TCL추진
-------	-------

TCL 类型

PCL상면

PCL상표

TCL 47	TCL 상면
--------	--------

TCL상면

12 (09/09)

(0109)

TCL상면	TCL측면
-------	-------

TCL 集团

PCL상면

PCL상면

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.2 mm	0.6 m		56	0.1 mm			
2	균열	0.1 mm	0.1 m		57				
3	균열	0.1 mm	0.6 m		58				
4	간격부 균열	0.3 mm	0.3 m		59				
5	간격부 균열	0.3 mm	0.3 m		60				
6	균열	0.1 mm	0.4 m		61				
7	균열	0.1 mm	0.8 m		62				
8	균열	0.1 mm	0.4 m		63				
9	균열	0.1 mm	0.4 m		64				
10	균열	0.1 mm	0.4 m		65				
11	균열	0.1 mm	0.7 m		66				
12	균열	0.1 mm	0.4 m		67				
13	균열	0.2 mm	0.8 m		68				
14	균열	0.1 mm	0.4 m		69				
15	균열	0.1 mm	0.65 m		70				
16	균열	0.1 mm	0.4 m		71				
17	균열	0.1 mm	0.6 m		72				
18	균열	0.2 mm	0.8 m		73				
19	균열	0.1 mm	0.4 m		74				
20	균열	0.1 mm	0.65 m		75				
21	균열	0.1 mm	0.4 m		76				
22	균열	0.1 mm	0.6 m		77				
23	균열	0.1 mm	0.6 m		78				
24	균열	0.1 mm	0.4 m		79				
25	균열	0.2 mm	0.7 m		80				
26	균열	0.1 mm	0.8 m		81				
27	균열	0.1 mm	0.4 m		82				
28	균열	0.1 mm	0.3 m		83				
29	균열	0.1 mm	0.4 m		84				
30	균열	0.2 mm	0.65 m		85				
31	균열	0.1 mm	0.1 m		86				
32	균열	0.1 mm	0.4 m		87				
33	균열	0.1 mm	0.8 m		88				
34	균열	0.1 mm	0.4 m		89				
35	균열	0.1 mm	0.6 m		90				
36	균열	0.1 mm	0.4 m		91				
37	간격부 균열	0.3 mm	0.3 m		92				
38	균열	0.1 mm	0.4 m		93				
39	균열	0.1 mm	0.6 m		94				
40	균열	0.1 mm	0.4 m		95				
41	균열	0.1 mm	0.7 m		96				
42	균열	0.2 mm	0.8 m		97				
43	균열	0.1 mm	0.4 m		98				
44	균열	0.1 mm	0.4 m		99				
45	균열	0.3 mm	0.3 m		100				
46	평상 균열	0.4 m	0.3 m		101				
47	균열	0.1 mm	0.4 m		102				
48	균열	0.1 mm	0.4 m		103				
49	균열	0.1 mm	0.4 m		104				
50	균열	0.1 mm	0.4 m		105				
51	균열				106				
52					107				
53					108				
54					109				
55					110				

[illegible]