

호남고속선 장구교_145(49.503~49.510km, S29-4)

PCL상면
49K503

49K510
29 SPAN -4

TCL	TCL
상면	상면

TM.278.1

TM.094.2

아
0

(아호)

TCL 상면	TCL 추면
--------	--------

PCL 상면

TCL 측면	TCL 상면
--------	--------

TM.252.2

12 (2014)

$$\begin{pmatrix} 0 > \\ 0 \text{와} \end{pmatrix}$$

TCL 상면	TCL 추면
--------	--------

 1.0^{-}

PCL상면

1111

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.3 m	m	55				
2	균열	0.1 mm	0.4 m		56				
3	균열	0.1 mm	0.4 m		57				
4	경계부 균열	0.3 mm	0.3 m		58				
5	균열	0.1 mm	0.4 m	m	59				
6	균열	0.1 mm	0.5 m	m	60				
7	균열	0.1 mm	0.5 m	m	61				
8	균열	0.2 mm	0.7 m	m	62				
9	균열	0.1 mm	0.6 m	m	63				
10	균열	0.2 mm	0.5 m	m	64				
11	균열	0.1 mm	0.3 m	m	65				
12	균열	0.1 mm	0.4 m	m					
13	균열	0.1 mm	0.4 m	m	67				
14	균열	0.1 mm	0.4 m	m	68				
15	균열	0.1 mm	0.4 m	m	69				
16	균열	0.1 mm	0.4 m	m	70				
17	균열	0.1 mm	0.4 m	m	71				
18	균열	0.1 mm	0.4 m	m	72				
19	균열	0.1 mm	0.4 m	m	73				
20	균열	0.2 mm	0.4 m	m	74				
21	균열	0.1 mm	0.4 m	m	75				
22	균열	0.1 mm	0.4 m	m	76				
23	경계부 균열	0.2 mm	0.3 m	m	77				
24	균열	0.1 mm	0.3 m	m	78				
25	균열	0.1 mm	0.4 m	m	79				
26	균열	0.1 mm	0.2 m	m	80				
27	균열	0.1 mm	0.2 m	m	81				
28	균열	0.1 mm	0.3 m	m	82				
29	균열	0.1 mm	0.4 m	m	83				
30	균열	0.1 mm	0.4 m	m	84				
31	균열	0.1 mm	0.4 m	m	85				
32	균열	0.1 mm	0.4 m	m	86				
33	균열	0.1 mm	0.3 m	m	87				
34	균열	0.1 mm	0.3 m	m	88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시	행 사	영 역	영 역	영 역	사	이 부 영		구 분	
						과 일 전 입 지	정 보 이 별 책 입 지		
KORAIL KOREA RAILROAD	한국철도공사	2017년도 호남고속선 오송-광주승정간 콘크리트캐드 점검공역	(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원	이 부 영	김 윤 강 김 경 기 문 석 기	구 분	 0220 (0.3m이하 : 철석)	 점목도상분리	
							 0420 (0.3m초과 0.5m이하 : 형석)	 망상	 철근노출
							 0620 (0.5m초과 1.0m미만 : 적석)	 반리, 반리, 표준	 누수, 슬래브
							 1020 (1.0m이상 : 불용석)	 백태	 시공이음분리, 종분리
									