

호남고속선 장구교-195(49.853~49.860km, S39-4)

49K853

49K860

39 SPAN - 4

PCL상면

TCL	TCL
상면	상면

TM.028.4

TM.239.2

$$\left(\frac{a}{a+b} \right)$$

TCL상면	TCL측면
-------	-------

PCL 상품

TCL 4K	TCL 상미
--------	--------

TM.091.1

12 (주) 호

TCL 상면	TCL 측면
--------	--------

PCL상면

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.75 m		55				
2	균열	0.1 mm	0.75 m		56				
3	균열	0.1 mm	0.6 m		57				
4	균열	0.1 mm	0.4 m		58				
5	균열	0.1 mm	0.75 m		59				
6	균열	0.1 mm	0.3 m		60				
7	균열	0.1 mm	0.6 m		61				
8	균열	0.1 mm	0.3 m		62				
9	균열	0.1 mm	0.7 m		63				
10	균열	0.1 mm	0.7 m		64				
11	균열	0.1 mm	0.7 m		65				
12	경계부 균열	0.3 mm	0.3 m		66				
13	경계부 균열	0.3 mm	0.3 m		67				
14	균열	0.1 mm	0.7 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.5 m		72				
19	균열	0.1 mm	0.4 m		73				
20	균열	0.1 mm	0.4 m		74				
21	균열	0.1 mm	0.4 m		75				
22	균열	0.1 mm	0.4 m		76				
23	균열	0.1 mm	0.4 m		77				
24	경계부 균열	0.3 mm	1.0 m	신규	78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역	영역	영역	사	과	장	영역	지	구분																
					개	입				전	지														
KORAIL KOREA RAILROAD 한국철도공사	2017년도 호남고속선 오송-광주승경간 콘크리트캐드 점검공역	(주) 한국구조물안전연구원 (주) 한국국토안전연구원 (재) 한국건설품질연구원	이 부 영	김윤강 김경기 문적기	영원		0220 (0.3m이하 : 흑색)		재료판리																
											0420 (0.3m초과 0.5m이하 : 청색)		망상												
															0620 (0.5m초과 1.0m이하 : 적색)		박리, 박락, 파손								
																			1020 (1.0m이상 : 분홍색)		백태				
																							0820 (0.5m이하 : 노란색)		노후, 슬관부