

화남고속선종리터널-토공노반-159(55.850~55.860km, L=10m)

The figure is a technical drawing of a 15x15 grid of square cells, likely a microarray or a similar scientific instrument. The grid is divided into four quadrants by a central horizontal and vertical line. Each cell contains a number from 1 to 15, representing a specific feature or measurement. The drawing includes various labels and annotations, such as 'TM 279.4', 'TM 263.2', 'TM 226.4', and 'TM 244.2', which likely refer to specific wavelengths or temperatures. The grid is surrounded by a border with labels like 'HSB상면' (HSB top surface) and 'TCL상면' (TCL top surface). The overall layout is symmetrical and precise, typical of a scientific or technical illustration.

연번	순상	폭	연장	비고	연번	순상	폭	연장m	비고
1	균열	0.1 mm	0.5 m	m	55	장계부 균열	0.2 mm	0.6 m	
2	균열	0.1 mm	0.8 m	m	56	균열	0.1 mm	0.4 m	
3	장계부 균열	0.3 mm	0.3 m		57	균열	0.1 mm	0.4 m	
4	균열	0.1 mm	0.8 m	m	58	균열	0.1 mm	0.4 m	
5	균열	0.1 mm	0.8 m	m	59	균열	0.1 mm	0.4 m	
6	균열	0.1 mm	0.4 m	m	60	장계부 균열	0.2 mm	0.2 m	
7	장계부 균열	0.3 mm	0.3 m		61	균열	0.1 mm	0.4 m	
8	균열	0.1 mm	0.5 m	m	62	균열	0.1 mm	0.4 m	
9	균열	0.1 mm	0.8 m	m	63	균열	0.1 mm	0.4 m	
10	균열	0.1 mm	0.4 m	m	64	균열	0.1 mm	0.4 m	
11	장계부 균열	0.3 mm	0.3 m	m	65	균열	0.1 mm	0.4 m	
12	균열	0.1 mm	0.8 m	m	66	균열	0.1 mm	0.4 m	
13	균열	0.1 mm	0.4 m	m	67	균열	0.1 mm	0.4 m	
14	균열	0.1 mm	0.8 m	m	68	균열	0.1 mm	0.8 m	
15	장계부 균열	0.3 mm	0.3 m	m	69	장계부 균열	0.2 mm	0.4 m	
16	균열	0.1 mm	0.4 m	m	70	균열	0.1 mm	0.4 m	
17	균열	0.1 mm	0.5 m	m	71	균열	0.1 mm	0.4 m	
18	균열	0.1 mm	0.8 m	m	72	균열	0.1 mm	0.4 m	
19	균열	0.1 mm	0.9 m	m	73	균열	0.1 mm	0.8 m	
20	균열	0.1 mm	0.4 m	m	74	균열	0.1 mm	0.4 m	
21	균열	0.1 mm	0.5 m	m	75	균열	0.1 mm	0.4 m	
22	균열	0.1 mm	0.8 m	m	76	장계부 균열	0.2 mm	0.3 m	
23	장계부 균열	0.3 mm	0.5 m	m	77	균열	0.1 mm	0.8 m	
24	장계부 균열	0.3 mm	0.3 m	m	78	균열	0.1 mm	0.4 m	
25	균열	0.1 mm	0.5 m	m	79	균열	0.1 mm	0.4 m	
26	장계부 균열	0.3 mm	0.3 m	m	80	균열	0.1 mm	0.8 m	
27	균열	0.1 mm	0.4 m	m	81	균열	0.1 mm	0.8 m	
28	균열	0.1 mm	0.8 m	m	82	층 분리	0.3 mm	10.0 m	신규
29	균열	0.1 mm	0.3 m	m	83	균열	0.3 mm	1.0 m	신규
30	균열	0.1 mm	0.4 m	m	84	균열	0.3 mm	1.0 m	
31	균열	0.1 mm	0.4 m	m	85				
32	균열	0.1 mm	0.4 m	m	86				
33	균열	0.1 mm	0.4 m	m	87				
34	균열	0.1 mm	0.4 m	m	88				
35	균열	0.1 mm	0.4 m	m	89				
36	장계부 균열	0.2 mm	0.2 m	m	90				
37	장계부 균열	0.2 mm	0.6 m	m	91				
38	장계부 균열	0.2 mm	0.2 m	m	92				
39	균열	0.1 mm	0.4 m	m	93				
40	장계부 균열	0.2 mm	0.6 m	m	94				
41	균열	0.1 mm	0.8 m	m	95				
42	균열	0.1 mm	0.4 m	m	96				
43	장계부 균열	0.2 mm	0.6 m	m	97				
44	균열	0.1 mm	0.4 m	m	98				
45	균열	0.1 mm	0.4 m	m	99				
46	균열	0.1 mm	0.4 m	m	100				
47	균열	0.1 mm	0.4 m	m	101				
48	균열	0.1 mm	0.4 m	m	102				
49	균열	0.1 mm	0.4 m	m	103				
50	균열	0.1 mm	0.4 m	m	104				
51	균열	0.1 mm	0.4 m	m	105				
52	장계부 균열	0.2 mm	0.4 m	m	106				
53	균열	0.1 mm	0.4 m	m	107				
54	장계부 균열	0.2 mm	0.3 m	m	108				

시행사	영역	영역	영역	시	인		단		
					개입책임자	평가책임자			
 KORAIL 한국철도공사 KOREA RAILROAD	영역	영역	영역	시	이	영	영		
								(주)한국철도공사 (주)한국철도공사 (주)한국철도공사 (주)한국철도공사	철물집 임경원 정재경
	0220 (0.300이하 : 역식)		천문교열분기		차로분기				
	0420 (0.30초과 0.50이하 : 형식)		양상		철근노출				
	0620 (0.50초과 1.00이하 : 직식)		바리,바리,표선		누수,슬럼프				
	1020 (1.00이상 : 분출식)		번대		오공				
							시공이음분기, 총분기		