

호남고속선 정지고가 410(59.754~59.761km, S78-3)

59K754

59K761
78 SPAN - 3

PCL상면

TCL 3000	TCL 3000
----------	----------

TM.246.2

TM.252.2

TCL 4000	TCL 4000
----------	----------

[illegible]

PCL 시스템

TCL 상용	TCL 추후
--------	--------

TM.250.2

1	
2	
3	
4	
5	
6	
7	
8	
9	
10	
11	

TCL 40	TCL 40
TCL 40	TCL 40

1401

PCL상면

1121

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.6 m		55				
2	균열	0.1 mm	0.3 m		56				
3	균열	0.1 mm	0.4 m		57				
4	균열	0.1 mm	0.4 m		58				
5	균열	0.1 mm	0.7 m		59				
6	균열	0.1 mm	0.7 m		60				
7	균열	0.1 mm	0.3 m		61				
8	균열	0.1 mm	0.3 m		62				
9	균열	0.1 mm	0.3 m		63				
10	균열	0.1 mm	0.7 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.6 m		72				
19	균열	0.1 mm	0.7 m		73				
20	균열	0.1 mm	0.3 m		74				
21	균열	0.1 mm	0.7 m		75				
22	균열	0.1 mm	0.7 m		76				
23	균열	0.1 mm	0.4 m		77				
24	균열	0.1 mm	0.4 m		78				
25	균열	0.1 mm	0.2 m		79				
26	균열	0.2 mm	0.2 m		80				
27	균열	0.1 mm	0.4 m		81				
28	균열	0.1 mm	0.4 m		82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

KORAIL 한국철도공사 KOREA RAILCO									
시	공	사	공	역	명	공	역	사	이 복 영
2017년도 화남고속선 오송-광주승강간 콘크리트케도 점검용역									
(주) 한국구조물안전연구원						라 안 강			
(주) 한국토목안전연구회						김 경 기			
(제) 한국건설품질연구원						문 석 기			
구 간									
 0.220 (0.30m)하 : 특색									
 0.420 (0.50m)초과 0.50m)하 : 형색									
 0.620 (0.50m)초과 1.00m)미만 : 정색									
 1.020 (1.00m)이상 : 반통색									
 원록도상신호리									
 망상									
 누수습윤부									
 시공이음관리종단리									
 재로분리									
 철근노출									
									