

호남고속선 정지고가 496(60.364~60.372km, S95-4)

60K364

60K372
95 SPAN - 4

PCL상표

TCL 3000	TCL 3000
----------	----------

TM 278.4	(7)	16.0.2	
	(10)	16.0.2	
	(12)	16.0.2	
	(13)	16.0.2	
	(14)	16.0.2	
TM 216.4			

TM.216.4

TCL 40	TCL 40
--------	--------

[illegible]

0.3/0.3

PCL 시스템

TCL 4000	TCL 4000
----------	----------

	②	③	④	
	16.0.1/0.	16.0.1/0.	16.0.1/0.	
TM.267.4				TM.097.1

TM.097.1

TCL 50吋	TCL 42吋
---------	---------

	1	
	2	
	3	
	4	
	5	
(20) 16.0.1/0.7	6	
	7	(20) 16.0.1/0.4 (20) 16.0.1/0.4
	8	
	9	
	10	
	11	
	12	
	13	

PCL상면

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		55				
2	균열	0.1 mm	0.3 m		56				
3	균열	0.1 mm	0.3 m		57				
4	균열	0.1 mm	0.3 m		58				
5	균열	0.1 mm	0.3 m		59				
6	균열	0.1 mm	0.3 m		60				
7	균열	0.2 mm	0.4 m		61				
8	균열	0.2 mm	0.3 m		62				
9	균열	0.2 mm	0.4 m		63				
10	균열	0.2 mm	0.5 m		64				
11	균열	0.2 mm	0.6 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.4 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.4 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18	균열	0.1 mm	0.4 m		72				
19	균열	0.2 mm	0.7 m		73				
20	균열	0.2 mm	0.5 m		74				
21	균열	0.1 mm	0.3 m		75				
22	균열	0.1 mm	0.7 m		76				
23	균열	0.1 mm	0.7 m		77				
24	균열	0.1 mm	0.5 m		78				
25	균열	0.1 mm	0.4 m		79				
26	균열	0.1 mm	0.4 m		80				
27	균열	0.1 mm	0.3 m		81				
28	균열	0.1 mm	0.7 m		82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]