

호남고속선 정지코가_532(60.618~60.625km, S102-5)

60K618

P102
60K625
102 SPAN -5

PCL상면

TCL 3000	TCL 3000
----------	----------

TM.221.3

TM.107.4

0.3		
-----	--	--

①

	v
--	-----

1
2
3
4
5
6
7
8
9
10
11

TCL 5000	TCL 5000
----------	----------

[illegible]

PCL 시험

TCL 泰康	TCL 泰康
TCL 泰康	TCL 泰康

TM.226.4

0.1/0

1

0.1/C

0.1/0.

0.170

0/1-r

0/1	
-----	--

247.2

1	
2	
3	
4	
5	7
6	5
7	7
8	7
9	7
10	
11	

7

c

+

④

 $\angle$

6

8

10

TCL 4000	TCL 4000
----------	----------

1001

PCL상면

1101

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.1 mm	0.4 m			55				
2	균열 0.1 mm	0.4 m			56				
3	균열 0.2 mm	0.5 m			57				
4	균열 0.1 mm	0.4 m			58				
5	균열 0.1 mm	0.4 m			59				
6	균열 0.1 mm	0.3 m			60				
7	균열 0.1 mm	0.2 m			61				
8	균열 0.2 mm	0.4 m			62				
9	균열 0.1 mm	0.7 m	m		63				
10	균열 0.1 mm	0.7 m			64				
11	균열 0.1 mm	0.5 m			65				
12	균열 0.1 mm	0.7 m			66				
13	균열 0.1 mm	0.7 m			67				
14	균열 0.1 mm	0.7 m	m		68				
15	균열 0.1 mm	0.4 m			69				
16	균열 0.1 mm	0.4 m			70				
17	균열 0.1 mm	0.4 m			71				
18	균열 0.1 mm	0.4 m			72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]