

호남고속선 정지 고가_540(60.674~60.681km, S104-3)

60K674

60K681

104 SPAN -3

PCU상면

TCL측면

TCL상면

PCU상면

TM/274.3

TM/225.4

1

2

3

4

5

6

7

8

9

10

11

① 15.0,2/0.5

② 15.0,1/0.4

③ 15.0,2/0.5

④ 16.0,1/0.7

TM/250.4

TM/256.1

1

2

3

4

5

6

7

8

9

10

11

⑤ 15.0,2/0.3

⑥ 16.0,1/0.4

⑦ 16.0,1/0.4

⑧ 16.0,1/0.4

⑨ 15.0,1/0.3

⑩ 16.0,1/0.7

PCU 상면

연번	순차	폭	연장	비고	연번	순차	폭	연장	비고
1	경계부 균열	0.2 mm	0.5 m		55				
2	균열	0.1 mm	0.4 m		56				
3	경계부 균열	0.2 mm	0.5 m		57				
4	균열	0.2 mm	0.3 m		58				
5	균열	0.1 mm	0.3 m		59				
6	균열	0.1 mm	0.7 m		60				
7	균열	0.1 mm	0.7 m		61				
8	균열	0.1 mm	0.4 m		62				
9	균열	0.1 mm	0.4 m		63				
10	균열	0.1 mm	0.4 m		64				
11	균열	0.1 mm	0.7 m		65				
12					66				
13					67				
14					68				
15					69				
16					70				
17					71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

시행사	영역	영역명	영역사	이보영	영역	단	 0.220 (0.3mm이하 : 열색)  0.400 (0.3mm초과 0.5mm이하 : 황색)  0.620 (0.5mm초과 1.0mm이하 : 적색)  1.020 (1.0mm이상 : 분홍색)	정동도상판리 명상 박리 박락 파손 배터	 재료판리  철근노출  누수수염부  시공이음판리, 종판리
KORAIL 한국철도공사 KOREA RAIL LTD.	2017년도 호남고속선 오송광주승정간 토크리테코도 점검용역								