

호남고속선 정지 고가_545(60.709~60.716km, S105-3)

60K709

60K716
105 SPAN-3

PCL상면

TCL 集团	TCL 产业
--------	--------

TM.255.3

TM.274.4

1/0.4

1
2
3
4
5
6
7
8
9
10
11

TCL 405H	TCL 405H
TCL 405H	TCL 405H

0.1

PCL 4004

TCL 총면	TCL 상면
--------	--------

TM.216.3

TM.261.1

0.4

11

0.4

--	--

[illegible]

0.4

0.4

[illegible]

TCL 405	TCL 405
TCL 405	TCL 405

PCL상표

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m	m	56				
2	균열	0.2 mm	1.0 m	m	57				
3	균열	0.1 mm	0.4 m	m	58				
4	균열	0.1 mm	0.4 m	m	59				
5	균열	0.1 mm	0.4 m	m	60				
6	균열	0.1 mm	0.4 m	m	61				
7	균열	0.1 mm	0.4 m	m	62				
8	균열	0.1 mm	0.4 m	m	63				
9	균열	0.1 mm	0.4 m	m	64				
10	균열	0.1 mm	0.4 m	m	65				
11	균열	0.1 mm	0.4 m	m	66				
12	균열	0.1 mm	0.4 m	m	67				
13	균열	0.1 mm	0.4 m	m	68				
14	균열	0.1 mm	0.4 m	m	69				
15	경계부 균열	0.2 mm	0.8 m	m	70				
16	균열	0.1 mm	0.4 m	m	71				
17	균열	0.1 mm	0.4 m	m	72				
18	균열	0.1 mm	0.4 m	m	73				
19	균열	0.1 mm	0.4 m	m	74				
20	균열	0.1 mm	0.4 m	m	75				
21	균열	0.1 mm	0.4 m	m	76				
22	균열	0.1 mm	0.4 m	m	77				
23	균열	0.1 mm	0.4 m	m	78				
24	균열	0.1 mm	0.4 m	m	79				
25					80				
26					81				
27					82				
28					83				
29					84				
30					85				
31					86				
32					87				
33					88				
34					89				
35					90				
36					91				
37					92				
38					93				
39					94				
40					95				
41					96				
42					97				
43					98				
44					99				
45					100				
46					101				
47					102				
48					103				
49					104				
50					105				
51					106				
52					107				
53					108				
54									

[illegible]