

호남고속선 정지 고가_600(61.094~61.101km, S116-3)

61K094

61K101
116 SPAN-3

PCL상표

TCL 3000	TCL 3000
----------	----------

TM.235.1

TM.277.3

1	
2	
3	
4	
5	
6	$\textcircled{20} 16.0.1/0.4$
7	
8	
9	
10	
11	

TCL 4000	TCL 4000
----------	----------

—

0.7

16-0.2/1.0 ⑤

PCL 5000

TCL 3000	TCL 3000
----------	----------

TM.236.3

TM.275.1

1	$\sim 16^{-0.1}/0.4$	
2		
3	$\oplus 16^{-0.1}/0.5$	
4	$\oplus 16^{-0.1}/0.4$	
5	$\oplus 16^{-0.1}/0.4$	
6	$\oplus 16^{-0.1}/0.4$	
7		
8		
9		
10	$\oplus 16^{-0.1}/0.4$	
11		

PCL상면

연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.6 m		55				
2	균열	0.1 mm	0.4 m		56				
3	균열	0.1 mm	0.4 m		57				
4	균열	0.1 mm	0.7 m		58				
5	균열	0.1 mm	0.4 m		59				
6	균열	0.2 mm	1.0 m		60				
7	균열	0.1 mm	0.4 m		61				
8	균열	0.1 mm	0.4 m		62				
9	균열	0.1 mm	0.4 m		63				
10	균열	0.1 mm	0.4 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.1 mm	0.4 m		66				
13	균열	0.1 mm	0.5 m		67				
14	균열	0.1 mm	0.4 m		68				
15	균열	0.1 mm	0.5 m		69				
16	균열	0.1 mm	0.4 m		70				
17	균열	0.1 mm	0.4 m		71				
18					72				
19					73				
20					74				
21					75				
22					76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

[illegible]