


호남고속선 정지코가_632(61.317~61.324km, S122-5)

61K324

61K317

122 SPAN - 5



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열	0.1 mm	0.4 m		55				
2	균열	0.1 mm	0.4 m		56				
3	강계부 균열	0.2 mm	0.3 m		57				
4	강계부 균열	0.2 mm	0.3 m		58				
5	균열	0.1 mm	0.4 m		59				
6	균열	0.1 mm	0.4 m		60				
7	균열	0.1 mm	0.4 m		61				
8	균열	0.1 mm	0.3 m		62				
9	균열	0.1 mm	0.7 m		63				
10	균열	0.1 mm	0.4 m		64				
11	균열	0.1 mm	0.4 m		65				
12	균열	0.3 mm	5.5 m		66				
13	균열	0.2 mm	1.5 m		67				
14	균열	0.2 mm	1.5 m		68				
15	균열	0.2 mm	1.5 m		69				
16	균열	0.1 mm	0.3 m		70				
17	균열	0.1 mm	0.7 m		71				
18	균열	0.1 mm	0.6 m		72				
19	균열	0.1 mm	0.4 m		73				
20	균열	0.1 mm	0.4 m		74				
21	균열	0.1 mm	0.3 m		75				
22	균열	0.1 mm	0.3 m		76				
23					77				
24					78				
25					79				
26					80				
27					81				
28					82				
29					83				
30					84				
31					85				
32					86				
33					87				
34					88				
35					89				
36					90				
37					91				
38					92				
39					93				
40					94				
41					95				
42					96				
43					97				
44					98				
45					99				
46					100				
47					101				
48					102				
49					103				
50					104				
51					105				
52					106				
53					107				
54					108				

 한국철도공사 KOREA RAILROAD	시	광역시	공	여	명	공	여	사	(주) 한국구조물안전연구원 (주) 한라토목안전연구원 (제) 한국건설품질연구원	이 복 영	김 완 기 문 석 기	조민						
													구	과	업	장		
														관	리	지		
														관	리	지		
														0.220 (0.3mm이하 : 적색)	천문도상판리		재로판리	
														0.420 (0.3mm초과 0.5mm이하 : 청색)	양산		철근노출	
														0.620 (0.5mm초과 1.0mm이하 : 적색)	바리,바리,파산		누수유무	
														1.020 (1.0mm이상 : 분홍색)	변태		시공이음판리(종판리)	