


호남고속선 신작교_72(66.975~66.982km, S15-1)



연번	순상	폭	연장	비고	연번	순상	폭	연장	비고
1	균열 0.2 mm	0.7 m		55					
2	균열 0.2 mm	0.7 m		56					
3	균열 0.2 mm	0.7 m		57					
4	균열 0.2 mm	0.3 m		58					
5	균열 0.2 mm	0.4 m		59					
6	균열 0.2 mm	0.4 m		60					
7	균열 0.2 mm	0.4 m		61					
8	균열 0.2 mm	0.4 m		62					
9	균열 0.2 mm	0.4 m		63					
10	균열 0.2 mm	0.4 m		64					
11	균열 0.2 mm	0.4 m		65					
12	균열 0.2 mm	0.4 m		66					
13	균열 0.6 m	6.5 m		67					
14	균열 0.1 mm	0.4 m		68					
15	균열 0.1 mm	0.4 m		69					
16	균열 0.1 mm	0.3 m		70					
17	균열 0.1 mm	0.4 m		71					
18	균열 0.2 mm	0.7 m		72					
19	균열 0.2 mm	0.7 m		73					
20	균열 0.1 mm	0.4 m		74					
21	균열 0.1 mm	0.4 m		75					
22	균열 0.1 mm	0.4 m		76					
23				77					
24				78					
25				79					
26				80					
27				81					
28				82					
29				83					
30				84					
31				85					
32				86					
33				87					
34				88					
35				89					
36				90					
37				91					
38				92					
39				93					
40				94					
41				95					
42				96					
43				97					
44				98					
45				99					
46				100					
47				101					
48				102					
49				103					
50				104					
51				105					
52				106					
53				107					
54				108					

시	행	사	공	역	명	공	역	사	과업책임자			연	구분								
									책임	책임	책임		구분	구분	구분						
KORAIL 한국철도공사 KOREA RAILROAD									2017년도 호남고속선 오송-광주승장간 콘크리트케도 점검용역			(주)한국구조물안전연구원 (주)한국국토안전연구원 (제)한국건설품질연구원			이복영			연	구분		
									간윤강 김정기 윤석기												
									〰〰												