




I D :U-T-S1~S3

과천
↑




↓
반포

[KEY PLAN]





I D :U-T-S4~S6

과천
↑




↓
반포

[KEY PLAN]





I D :U-T-S7~S9

과천
↑




↓
반포

[KEY PLAN]





I D :U-T-S10~S12

과천
↑




↓
반포

[KEY PLAN]





I D :U-T-S13~S15

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S16~S18

과천
↑

0+670 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S18

0+660

S17

0+650



S16

0+640

↓
반포

①도랑박리
0.3x0.3 X5EA

[KEY PLAN]



I D :U-T-S19~S21

과천
↑

0+700

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S21

0+690

S20

0+680



타월물막
2EA

S19

0+670

↓
반포

[KEY PLAN]



I D :U-T-S22~S24

과천
↑

외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

0+725

S24

0+720

S23

0+710

S22



0+700

① 공동구 균열 소
0.2/1.0


② 공동구 균열 소
0.6/0.3

↓
반포


[KEY PLAN]



I D :U-T-S25~S27




[KEY PLAN]





I D :U-T-S28~S30

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S31~S33

과천
↑

0+815

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S33

0+805

S32

0+795

S31



0+785

① 공동구 덮개 박락
0.1X0.1

② 공동구 들뜸
0.1X0.5

↓
반포

[KEY PLAN]



I D :U-T-S34~S36

과천
↑

0+845

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S36

① 공동구 덮개 파손
2EA

0+835

S35



0+825

S34

0+815

↓
반포

[KEY PLAN]



I D :U-T-S37~S39

과천
↑

0+875 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S39

0+865

S38

0+855



S37

S8

0+845

↓
반포

[KEY PLAN]



I D :U-T-S40~S42

과천
↑

0+904.189

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S42

0+894.189

S41

0+885



S40

0+875

① 평면기울기 0.3/0.5
↓

↓
반포

[KEY PLAN]



I D :U-T-S43~S45

과천
↑

0+934.189 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S45

① 공동구 덮개 파손
1EA


② 공동구 덮개 파손
1EA

0+924.189

S44

0+914.189



S43
피난연결통로



0+904.189

↓
반포

[KEY PLAN]



I D :U-T-S46~S48

과천
↑

0+961

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S48

54

0+951

S47



0+944.189

S46

0+934.189


↓
반포

[KEY PLAN]





I D :U-T-S49~S51

과천
↑




↓
반포

[KEY PLAN]





I D :U-T-S52~S54

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S55~S57

과천
↑

1+51 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S57

1+41

① 공동구 파손
0.2X0.2

S56

② 타일틀락
1EA



1+31

S55

1+21


↓
반포

[KEY PLAN]





I D :U-T-S58~S60

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S61~S63

과천
↑

1+111

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S63

① 타일탈락
2EA

소

48

1+101

S62



1+91

S61

1+81

↓
반포

[KEY PLAN]



I D :U-T-S64~S66

과천
↑

1+141

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S66

1+131

S65



1+121

S64

1+111

↓
반포

[KEY PLAN]



I D :U-T-S67~S69

과천
↑

1+171 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S69

1+161

S68

1+151



S67

1+141

소
46

↓
반포

[KEY PLAN]



I D :U-T-S70~S72

과천
↑

1+201 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S72

1+191

S71



1+181

S70

1+171

↓
반포

[KEY PLAN]



I D :U-T-S73~S75

과천
↑

1+231 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S75

1+221

S74

1+211



S73

1+201


44

↓
반포


[KEY PLAN]



I D :U-T-S76~S78



[KEY PLAN]



I D :U-T-S79~S81

과천
↑

1+291 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S81

① 타일탈락
13EA

1+281

S80



1+271

S79

1+261

↓
반포

[KEY PLAN]



I D :U-T-S82~S84

과천
↑

1+321

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S84

1+311

S83

1+301



S82

1+291

40

↓
반포

[KEY PLAN]



I D :U-T-S85~S87

과천
↑

1+351

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S87

1+341

S86

1+331

S85



1+321

38

소

↓
반포

[KEY PLAN]



I D :U-T-S88~S90

과천
↑

1+381

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S90

소

1+371

S89



1+361

S88

1+351

↓
반포

[KEY PLAN]



I D :U-T-S91~S93

과천
↑

1+411

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S93

1+401

36

S92


1+391

S91

1+381

↓
반포

[KEY PLAN]



I D :U-T-S94~S96

과천
↑

1+441

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S96

① 타일탈락
10EA

1+431

S95

소

1+421



S94

② 타일탈락
7EA

1+411

↓
반포

[KEY PLAN]



I D :U-T-S97~S99

과천
↑

1+468.734

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S99

1+461

S98



1+451

S97

1+441

↓
반포

[KEY PLAN]



I D :U-T-S100~S102

과천
↑

1+498.734 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S102

1+488.734

S101



1+478.734

S100

1+468.734

↓
반포

[KEY PLAN]



I D :U-T-S103~S105

과천
↑

1+528.734 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S105

0+518.734

S104

소

1+508.734

S103
피난연결통로



32

1+498.734

① 박리
0.1X0.3

반포
↓

[KEY PLAN]



I D :U-T-S109~S111

과천
↑

1+581

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

다열탈락
18EA

S111

1+571

S110

1+561

S109



1+551

소

30

↓
반포

[KEY PLAN]



I D :U-T-S112~S114

과천
↑

1+611 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S114

28

소

1+601

제트펜

제트펜

S113



1+591

S112

1+581

↓
반포

[KEY PLAN]



I D :U-T-S115~S117

과천
↑

1+641 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S117

1+631

S116



1+621

S115

1+611

↓
반포

[KEY PLAN]



I D :U-T-S118~S120

과천
↑

1+671 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S120

1+661

S119

1+651

S118


1+641

26

△

↓
반포

[KEY PLAN]



I D :U-T-S121~S123

과천
↑

1+701 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S123

소

1+691

S122



1+681

S121

1+671

↓
반포

[KEY PLAN]



I D :U-T-S124~S126

과천
↑

1+731

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S126

1+721

S125

1+711

S124



1+701

24

① 공동구 덮개 파손
2EA

↓
반포

[KEY PLAN]



I D :U-T-S127~S129

과천
↑

1+761 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S129

1+751

S128

1+741

S127

1+731

22



제트펜

제트펜


스

↓
반포


[KEY PLAN]



I D :U-T-S130~S132



[KEY PLAN]



I D :U-T-S133~S135

과천
↑

1+821

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S135

1+811

S134

1+801

S133

1+791

20

신호기

① 공동구
1EA



② 공동구
1EA

덮개 파손

덮개 파손

↓
반포

[KEY PLAN]



I D :U-T-S136~S138

과천
↑

1+851

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S138

1+841

S137

1+831

S136

1+821



① 공동구 덮개 파손
1EA





② 공동구 덮개 파손
3EA




↓
반포


[KEY PLAN]



I D :U-T-S139~S141



[KEY PLAN]



I D :U-T-S142~S144

과천
↑

1+911

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S144

1+901

16

S143



1+891

S142

1+881

↓
반포

[KEY PLAN]



I D :U-T-S145~S147

과천
↑

1+941 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S147

1+931

S146

1+921



소

S145

1+911

↓
반포

[KEY PLAN]



I D :U-T-S148~S150

과천
↑

1+971

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S150

1+961

소

S149

1+951

14



S148

1+941

타일
1EA


↓
반포

[KEY PLAN]





I D :U-T-S151~S153

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S154~S156

과천
↑

2+31 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S156

2+21

S155

제트펜

제트펜

2+11



수

S154

2+1


↓
반포

[KEY PLAN]





I D :U-T-S157~S159

과천
↑



↓
반포

[KEY PLAN]



I D :U-T-S160~S162

과천
↑

2+91 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S162

2+81

① 타일블락
4EA

S161



2+71

S160

2+61

↓
반포

[KEY PLAN]



I D :U-T-S163~S165

과천
↑

외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

2+115

S165

① 공동구 덮개 파손
1EA



2+105

S164

8

소

2+95



S163

② 타일탈락
51EA

2+91

↓
반포

[KEY PLAN]



I D :U-T-S166~S168

과천
↑

2+145 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S168


2+135

S167

2+125


S166

2+115




↓
반포

[KEY PLAN]



과천 →



I D :U-T-S169~S171

과천
↑

2+173.83

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S171

6

2+163.83

S170

제트펜

제트펜



2+154.35

S169

2+145

↓
반포

[KEY PLAN]



I D :U-T-S172~S174

과천
↑

2+203.83 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S174

4

2+193.83

S173

소

2+183.83



S172

① 공동구 규모
0.3/2.0

2+173.83

↓
반포

[KEY PLAN]



I D :U-T-S175~S177

과천
↑

2+232.53

외측공동구

Tile Line

Lining CL

Tile Line

내측공동구

Paving CL

S177

2+223.83

S176



2+213.83

S175

2+203.83

↓
반포

[KEY PLAN]




I D :U-T-S178~S180

과천
↑


2+262.53 외측공동구 Tile Line Lining CL Tile Line 내측공동구 Paving CL

S180




2+252.53

S179



2+242.53



S178



2+232.53


↓
반포

[KEY PLAN]





I D :U-T-S181~S183

과천
↑




↓
반포


[KEY PLAN]



I D :U-T-S184~S185





[KEY PLAN]





ID :U-T-집진기실-1

[SECTION]





[KEY PLAN]





ID :U-T-집진기실-2

[SECTION]




[KEY PLAN]




ID :U-T-집진기실-3


[SECTION]





1



2




[KEY PLAN]




I D : 피난연결통로

과천
↑





S46~S48




S106~S108

반포
↓

[KEY PLAN]



I D :U-T-집진기실-4



[KEY PLAN]

